

## **Unsafe Act or Condition**

Vessel : Bitu Atlantic					
Report Date: 11-Apr-2023					
Location : DECK					
Unsafe Act Or Condition:					
Type : Unsafe Condition					
Brief Details : Disconnection of Cargo hose from M.T Bitu River after Cargo opertation. The cargo hose received without all bolts in flange are not in place.					
Was action taken at the time? :		Yes	All flange bolts put in place and tighten, make sure that there is no any leak from the hose.		
Was work stopped? :		No	All flange bolts put in place and tighten, make sure that there is no any leak from the hose.		
Officer notified? :		Yes	informed oow		
Action successful? :		Yes			
Report anonymous? :		No	informed oow		
Any other comments or suggestions? Enter below:					
Brief Details : Good observation, Preventive measures must be implemented on priority. All cargo hoses must be blanked off by means of proper size of nuts & bolts.					
Date Reviewed by DPA : 19-Apr-2023					
Actions :					
Tick further Actions : No Further action re		required	Remarks :		
Link NC/Observation/Near Miss/ Risk Assessment :					
Followup Completed : Yes					