



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

| | | |
|---|----------------------------|---|
| Vessel : Bitu Atlantic | | |
| Report Date : 11-Apr-2023 | | |
| Location : DECK | | |
| Unsafe Act Or Condition: | | |
| Type : Unsafe Condition | | |
| Brief Details : Disconnection of Cargo hose from M.T Bitu River after Cargo operation. The cargo hose received without all bolts in flange are not in place. | | |
| Was action taken at the time? : | Yes | All flange bolts put in place and tighten, make sure that there is no any leak from the hose. |
| Was work stopped? : | No | All flange bolts put in place and tighten, make sure that there is no any leak from the hose. |
| Officer notified? : | Yes | informed oow |
| Action successful? : | Yes | |
| Report anonymous? : | No | informed oow |
| Any other comments or suggestions? Enter below: | | |
| Brief Details : Good observation, Preventive measures must be implemented on priority. All cargo hoses must be blanked off by means of proper size of nuts & bolts. | | |
| Date Reviewed by DPA : 19-Apr-2023 | | |
| Actions : | | |
| Tick further Actions : | No Further action required | Remarks : |
| Link NC/Observation/Near Miss/ Risk Assessment : | | |
| Followup Completed : Yes | | |