

Unsafe Act or Condition

Vessel : Bitu Atlantic					
Report Date : 11-Apr-2023					
Location : DECK					
Unsafe Act Or Condition:					
Type : Unsafe Act					
Brief Details : During de-fendering operation, one among the 4guard ropes got strucked in between the handrail. Crew was clearing the stucked rope and mean time the fender swing to other side & the secured gaurd rope was tighten up and got hit slightly on his helmet.					
Was action taken at the time?	': Yes	Immideatly swing the crane to opposite side and keep hold the other guard ropes to keep fender in position. Mean time the stucked rope was cleared.			
Was work stopped? :	No	Immideatly swing the crane to opposite side and keep hold the other guard ropes to keep fender in position. Mean time the stucked rope was cleared.			
Officer notified? :	Yes				
Action successful? :	Yes				
Report anonymous? :	No				
Any other comments or suggestions? Enter below:					
Brief Details : Supervision is must while handling fenders and the personnel handling crane must remain in sight of the supervisor to follow his order.					
Date Reviewed by DPA : 15-Apr-2023					
Actions :					
Tick further Actions : N	o Further actior	required	Remarks :		
Link NC/Observation/Near Miss/ Risk Assessment :					
Followup Completed : Yes					