

Followup Completed: Yes

## Maritec Tanker Management Unsafe Act or Condition

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

Rev Date

Vessel: Bitu Atlantic Report Date: 11-Apr-2023 Location: DECK Unsafe Act Or Condition: Type: Unsafe Condition Brief Details: Disconnection of Cargo hose from M.T Bitu River after Cargo opertation. The cargo hose received without all bolts in flange are not in place. Was action taken at the time? : All flange bolts put in place and tighten, make sure that there is no any leak Yes from the hose. Was work stopped?: No All flange bolts put in place and tighten, make sure that there is no any leak from the hose. Officer notified?: Yes informed oow Action successful?: Yes Report anonymous?: No informed oow Any other comments or suggestions? Enter below: Brief Details: Good observation, Preventive measures must be implemented on priority. All cargo hoses must be blanked off by means of proper size of nuts & bolts. Date Reviewed by DPA: 19-Apr-2023 Actions: Tick further Actions: No Further action required Remarks: Link NC/Observation/Near Miss/ Risk Assessment:

Unsafe Act or Condition Printed On: 26-Sep-2023 1/1