



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Atlantic		
Report Date : 24-Mar-2023		
Location : Deck		
Unsafe Act Or Condition:		
Type : Unsafe Act		
Brief Details : Crew member working aloft, working with Safety Harness, observed not considered the length of rope attached to harness, observed length of rope attached to harness was more than the height of working place and deck.		
Was action taken at the time? :	Yes	Crew member instructed to adjust the rope
Was work stopped? :	Yes	Crew member instructed to adjust the rope
Officer notified? :	No	Observed by Officer
Action successful? :	Yes	
Report anonymous? :	Yes	Observed by Officer
Any other comments or suggestions? Enter below:		
Brief Details : Very good observation, we concur with the action plan of the vessel.		
Date Reviewed by DPA : 29-Mar-2023		
Actions :		
Tick further Actions :	No Further action required	Remarks : Educate all the staff on this aspect.
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		