



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Atlantic		
Report Date : 24-Mar-2023		
Location : Deck		
Unsafe Act Or Condition:		
Type : Unsafe Condition		
Brief Details : while working aloft, crew member working with safety harness found not considered the lenth of rope attached to harness. Observed lenth was more than the height between work place to deck.		
Was action taken at the time? :	Yes	
Was work stopped? :	Yes	
Officer notified? :	No	Observed by officer
Action successful? :	Yes	
Report anonymous? :	Yes	Observed by officer
Any other comments or suggestions? Enter below:		
Brief Details : Seems to be the repeated observation as reported on same date.		
Date Reviewed by DPA : 29-Mar-2023		
Actions :		
Tick further Actions :	No Further action required	Remarks :
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		