



## Maritec Tanker Management

### Unsafe Act or Condition

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

Vessel : Bitu River		
Report Date : 12-Jun-2023		
Location : Pood deck / Durban / Maydon Wharf 7		
Unsafe Act Or Condition:		
Type : Unsafe Act		
Brief Details : During unmooring operation, 2 stern lines got stuck on the bollard due tight mooring rope from the other vessel moored on Wharf #- 6.		
Was action taken at the time? :	Yes	Instructed the incharge officer to stop heaving up and called the attention off the other vessel.
Was work stopped? :	Yes	Instructed the incharge officer to stop heaving up and called the attention off the other vessel.
Officer notified? :	Yes	
Action successful? :	Yes	Wait until the other vessel slacked their mooring lines before heaving up vessel reamining stern lines.
Report anonymous? :	Yes	
Any other comments or suggestions? Enter below:		
Brief Details : Concur with action plan.		
Date Reviewed by DPA : 20-Jun-2023		
Actions :		
Tick further Actions :	Raise Near Miss	Remarks : Raise one Nearmiss report for this.
Link NC/Observation/Near Miss/ Risk Assessment : Rags and cardboard sheet (pote		
Followup Completed : Yes		