



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu River		
Report Date : 14-Jun-2023		
Location : Deck		
Unsafe Act Or Condition:		
Type : Unsafe Act		
Brief Details : During mooring station, tug was made fast and crew member not clear from the bitts where tug line was made fast. The tug was not yet pulling but still after tug is made fast, crew members to keep clear.		
Was action taken at the time? :	Yes	Crew were informed to keep clear
Was work stopped? :	Yes	Tug informed to to pull the line
Officer notified? :	Yes	
Action successful? :	Yes	
Report anonymous? :	Yes	
Any other comments or suggestions? Enter below:		
Brief Details :		
Date Reviewed by DPA : N/A		
Actions :		