



## Maritec Tanker Management

### Unsafe Act or Condition

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

Vessel : Bitu River			
Report Date : 14-Jun-2023			
Location : Deck			
Unsafe Act Or Condition:			
Type : Unsafe Act			
Brief Details : During mooring station, tug was made fast and crew member not clear from the bits where tug line was made fast. The tug was not yet pulling but still after tug is made fast, crew members to keep clear.			
Was action taken at the time? :	Yes	Crew were informed to keep clear	
Was work stopped? :	Yes	Crew were informed to keep clear	
Officer notified? :	Yes		
Action successful? :	Yes		
Report anonymous? :	Yes		
Any other comments or suggestions? Enter below:			
Brief Details : Mooring operation must be considered critical one so all precautions must be taken with great care.			
Date Reviewed by DPA : 21-Jun-2023			
Actions :			
Tick further Actions :	No Further action required	Remarks :	Safe mooring practices needs to be discussed with all involved personnel in mooring operation.
Link NC/Observation/Near Miss/ Risk Assessment :			
Followup Completed : Yes			