



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu River		
Report Date : 16-Jun-2023		
Location : Deck		
Unsafe Act Or Condition:		
Type : Unsafe Condition		
Brief Details : During deck rounds at berth, the rope chafe guard was found not in proper position to guard the rope against chafing.		
Was action taken at the time? :	Yes	The rope adjusted to place rope chafe guard in proper position
Was work stopped? :	No	
Officer notified? :	Yes	
Action successful? :	Yes	
Report anonymous? :	No	
Any other comments or suggestions? Enter below:		
Brief Details :		
Date Reviewed by DPA : N/A		
Actions :		