



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

| | | |
|---------------------------------------------------------------------------------------------------------------------------------------|-----|----------------------------------------------------------------|
| Vessel : Bitu River | | |
| Report Date : 16-Jun-2023 | | |
| Location : Deck | | |
| Unsafe Act Or Condition: | | |
| Type : Unsafe Condition | | |
| Brief Details : During deck rounds at berth, the rope chafe guard was found not in proper position to guard the rope against chafing. | | |
| Was action taken at the time? : | Yes | The rope adjusted to place rope chafe guard in proper position |
| Was work stopped? : | No | |
| Officer notified? : | Yes | |
| Action successful? : | Yes | |
| Report anonymous? : | No | |
| Any other comments or suggestions? Enter below: | | |
| Brief Details : | | |
| Date Reviewed by DPA : N/A | | |
| Actions : | | |