



## Maritec Tanker Management

### Unsafe Act or Condition

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

Vessel : Bitu River		
Report Date : 16-Jun-2023		
Location : Deck		
Unsafe Act Or Condition:		
Type : Unsafe Condition		
Brief Details : During deck rounds at berth, the rope chafe guard was found not in proper position to guard the rope against chafing.		
Was action taken at the time? :	Yes	The rope adjusted to place rope chafe guard in proper position
Was work stopped? :	No	The rope adjusted to place rope chafe guard in proper position
Officer notified? :	Yes	
Action successful? :	Yes	
Report anonymous? :	No	
Any other comments or suggestions? Enter below:		
Brief Details : Agree with the action plan. Crew member must be reminded to remain observant while working/taking safety rounds on deck.		
Date Reviewed by DPA : 18-Jun-2023		
Actions :		
Tick further Actions :	No Further action required	Remarks :
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		