----- InnerException -----

The underlying connection was closed: An unexpected error occurred on a receive.

----- InnerException -----

The client and conver cannot communicate herause they do not noccess a

Remarks

Inspection Type 006 - Vessel Inspection Report

Inspection Date 25 Aug 2021

Inspector Jainish Bhatnagar

From Port Yalova

To Port Yalova

Hours Onboard 96 H

Avg Audit Findings 54 %

No of NCRs 0

No of observation 18

Crew Interview & Attendance Record

Staff Name Rank

Maritec Tanker Management Private Limited

Vessel - Bitu Express (IMO: 9265689)

An error has occurred while processing PictureBox 'pictureBox2':

Invalid image data.
-----InnerException ----The underlying connection was closed: An unexpected error occurred on a receive.
-----InnerException ----The client and server cannot communicate, because they do not possess a common algorithm

Auditor Signature

Maritec Tanker Management Private Limited

Vessel - Bitu Express (IMO: 9265689)

Jainish Bhatnagar

Negative Findings						
Defect ID Chapter	Category	Question	Answer Details	ls Critical	Status	Link

Additional	I NCRs			
Defect ID	NCR No	Observations	Date of Disposition	Status

Defect ID	Observations	Date of Disposition	Status
155	1.02.05 : The Thermal Boiler Room Fwd side and Accommodation aft side has lot of rust and weeping marks, requiring proper maintenance and painting. Same to be attended to and cosmetic appearance of superstructure to maintain.	01 Oct 2021	Completed
156	1.02.26 : The teflon packing on cargo domes has deteriorated and needs to be changed. Kindly renew the packing of all the Cargo tank domes.	24 Oct 2021	Completed
157	1.04.05: Lot of Rusted Gratings are lying on the top decks. To be disposed off if not fit for use on vessel. If found suitable for use, to be chipped and painted and stowed nicely.	02 Nov 2021	Completed
158	1.04.08: Midship stores to be cleaned and rearranged. Proper housekeeping standards to maintain on vessel.	13 Nov 2021	Completed
159	1.05.05 : Pump room Ballast water Lines: The nuts and bolts of filters and pipelines to be derusted and greased. U- clamps have started to rust. Same to be derusted and painted. Ballast Water Lines to be painted as per the paint scheme of the vessel	04 Oct 2021	Completed
160	1.06.02: Accommodation Ac Inlet mushroom on Stbd aft of the vessel is badly rusted/wasted. Mesh/ Mesh supports/ nuts bolts to renew.	11 Oct 2021	Completed
161	1.06.03: Main deck cosmetic upgradation to continue. Especially the cross-decks between the cargo manifold and accommodation superstructure. See attached pics for reference base on Item No. 1.06.03.		Pending
162	1.06.03: The main deck sides and alleyways especially on the Port Side were badly affected by the ship side painting done by the amateur painters in the OZATA shipyard. The same to be painted once the vessel receives the required paints.	05 Oct 2021	Completed

----- InnerException -----

The underlying connection was closed: An unexpected error occurred on a receive.

----- InnerException -----

Maritec Tanker Management Private Limited

- P. C. C.	nd server cannot communicate, herause they do not nossess a		
163	1.06.03: The catwalk gratings are badly rusted at a lot of places and the angle supports beneath them are wasted/rusted. Lot of angle supports were renewed by vessel staff during the drydocking. Same to be continued by the vessel in the ballast voyage after getting the required permissions from the office. The rusted gratings to be disposed off and new fibre gratings purchased for the vessel to be utilized in their place.	01 Oct 2021	Completed
164	1.06.08: Crew using the alleyways (and Engine room entrance) for drying their clothes. The practice needs to be stopped and clothes to be dried either in the dryers or drying rooms or cabins. This practice not only gives a well maintained accommodation a shabby look but is also a fire hazard.	03 Oct 2021	Completed
165	1.07.05 : Azimuth sensor of magnetic compass is defective. Same to be replaced with new spares on receipt.		Pending
166	10.08.01: ECR Dirty cups and even dirtier Tea/coffee making area- Hygiene needs to be maintained. Manuals and workbooks to be kept in their designated shelves and places. To give ECR a good and well maintained look.	04 Oct 2021	Completed
167	10.08.02a: A few exhaust leakage marks / paint peel off could be seen ME Turbocharger . This needs to be cleaned and painted with hig temperature silver Aluminium paint.	05 Oct 2021	Completed
168	10.08.01: The high voltage insulation mat in the ECR needs to be changed with the new received in the store.	05 Oct 2021	Completed
169	10.08.03: Main Sea water Pumps: Main Sea water pumps leaking from the mechanical seal. Vessel to overhaul the MSW pumps and raise requisition for spares.	05 Oct 2021	Completed
170	10.08.69: The Engine room under Mr. Pitic has been doing a good job of accounting the spares and matching the ROB as in JOT. The same needs to be continued till all spares are accounted for in JOT with the correct ROB. It is imperative that critical items are marked and along with the minimum major spares, an inventory is always maintained on the vessel.	01 Nov 2021	Completed
171	10.09.19: Engine room log book was observed to be written by the oilers in the Engine room. It must be implied on the watchkeeping Engineers to write the Engine room log book. The Engine room log books give a glimpse on the health of the machinery and the symptoms of the maintenance coming due before its time. And that's what preventive maintenance is all about.	05 Oct 2021	Completed
172	The vessel needs to update the saloon and deck stores inventory correctly in JOT at least before sending in the quarterly requisitions for the same. This will help the office in finalizing the correct quantities to be supplied and maintaining the correct ROB of various items on board.	09 Oct 2021	Completed

Positive / Neutral Findings					
Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.01 - External Condition - Propeller	Grade - Yes Answer Remark :	No	Link 1
01.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.02 - External Condition - Rudder	Grade - Yes Answer Remark :	No	Link 1
01.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.03 - External Condition - Ship's name and Port of Registry	Grade - Yes Answer Remark :	No	

----- InnerException -----

The underlying connection was closed: An unexpected error occurred on a receive.

----- InnerException -----

The client and conver cannot communicate herause they do not noscess a

Maritec Tanker Management Private Limited

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.04 - External Condition - Hull -	Grade - Yes	No	Link 1
		Topside area	Answer Remark :		Limbo
					Link 2
					Link 3
1.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.05 - External Condition - Hull - Boot	*·	No	Link 1
		top area	Answer Remark :		Link 2
					Link 3
1.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.06 - External Condition - Draft marks	Grade - Yes	No	Link 1
•			Answer Remark :		Link 2
					Link 3
					Link 4
1.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.07 - External Condition - Plimsoll	Grade - Yes	No	Link 1
		mark	Answer Remark :		
11.00 - Area/Item Inspected	01.01 - Part I - External Condition	01.01.08 - External Condition - Bow thruster / Bulb mark / tank marks	Grade - Yes Answer Remark :	No	
11.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.01 - Decks - Accommodation	Grade - Yes	No	
71.00 - Area/Rem mspecied	01:02 - Falt II - Decks	Ladders - Platform / Wires / Motor	Answer Remark :	NO	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.02 - Decks - Ships name - bridge	Grade - Yes	No	
7.00 7.00/1.011 moposiou	01.02 Farth Books	wings	Answer Remark :	140	
11.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.03 - Decks - MOT Gangway	Grade - Yes	No	
,		3 ,	Answer Remark :		
1.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.04 - Decks - Railings and Bulwark	Grade - Yes	No	
·		-	Answer Remark :		
1.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.05 - Decks - Superstructure / Funnel		No	Link 1
			Answer Remark :		
			Thermal boiler room fwd side and Accomodation		
			superstructure aft side needs to be painted.		
1.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.06 - Decks - Forecastle deck plating	Grade - Yes	No	
			Answer Remark :		
1.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.07 - Decks - Windlass	Grade - Yes	No	
			Answer Remark :		
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.08 - Decks - Anchor / cables - port	Grade - Yes	No	
		and STBD	Answer Remark :		
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.09 - Decks - Mooring ropes and	Grade - Yes	No	
•		wires	Answer Remark :		

----- InnerException -----

The underlying connection was closed: An unexpected error occurred on a

The client and server cannot communicate, because they do not

Maritec Tanker Management Private Limited

Chapter	Category	Question	Answer Details	ls Critical Link
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.10 - Decks - Mooring winches on	Grade - Yes	No
		forecastle deck	Answer Remark :	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.11 - Decks - Deck Light masts and	Grade - Yes	No
		fittings	Answer Remark :	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.12 - Decks - Forward mast	Grade - Yes	No
•			Answer Remark :	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.13 - Decks - Forward and aft Talk	Grade - Yes	No
·		back system	Answer Remark :	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.14 - Decks - Main deck plating	Grade - Yes	No
•			Answer Remark :	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15a - Pipelines - Ballast	Grade - Yes	No
•		•	Answer Remark :	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15b - Pipelines - Cargo	Grade - Yes	No
•			Answer Remark :	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15c - Pipelines - Steam/Thermal Oil	Grade - Yes	No
•		,	Answer Remark :	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15d - Pipelines - Fire	Grade - Yes	No
•		,	Answer Remark :	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15e - Pipelines - Foam	Grade - Yes	No
		Ф 3.00-1.10-1 У ф 2	Answer Remark :	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15f - Pipelines - Hydraulic	Grade - Yes	No
			Answer Remark :	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15g - Pipelines - Electrical conduit	Grade - Yes	No
		то по	Answer Remark :	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.15h - Pipelines - Insulation	Grade - Yes	No
		теления при	Answer Remark :	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.16 - Decks - Cargo manifold and drip		No
, , p = = = =	0 2 . a	tray/Various Pressure & Temp. gauges	Answer Remark :	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.17 - Decks - Air pipes / Sounding	Grade - Yes	No
, ,	0 2 . a	pipes / Filling pipes	Answer Remark :	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.18 - Decks - Cranes / Derricks and	Grade - Yes	No
, , p = = = =	01102 1 01111 2 00110	associated loose gear, motors and winches		
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.19 - Decks - Mooring winches on	Grade - Yes	No
,	01102 1 01111 2 00110	main deck	Answer Remark :	
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.20 - Decks - Aft deck / poop deck	Grade - Yes	No
7 i. ou 7 ii ou, ii oi ii ii ii opootou	onor raith books	plating	Answer Remark :	110
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.21 - Decks - Mooring winches on	Grade - Yes	No
7.1.00 7.1.00/1.0111 IIIopoolou	STOP THE BOOKS	aft / poop deck	Answer Remark :	110
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.22 - Decks - Condition of spare	, alono i tomant.	No
o 1.00 - Allou/Itom mapooled	VI.OZ - I GIT II - DOONS	propeller, anchor		140
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.23 - Decks - Monkey island deck	Grade - Yes	No
o 1.00 - Arca/Item mapecied	O 1.02 - Fait II - Deurs	plating	Answer Remark :	INO
		piauriy	Allower Neillain .	

----- InnerException -----

The underlying connection was closed: An unexpected error occurred on a receive.

----- InnerException -----

The client and conver cannot communicate herause they do not noscess a

Maritec Tanker Management Private Limited

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.24 - Decks - Main mast and fittings	Grade - Yes	No	
			Answer Remark :		
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.25a - Tugs - Towing winch	Grade - No	No	
			Answer Remark :		
			NA		
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.25b - Tugs - Deck rollers	Grade - No	No	
·		· ·	Answer Remark :		
			NA		
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.25c - Tugs - Fenders	Grade - No	No	
·		•	Answer Remark :		
			NA		
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.25d - Tugs - Aft control station	Grade - No	No	
·		· ·	Answer Remark :		
			NA		
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.26a - Tankers - Cargo tank domes	Grade - No	No	Link 1
·		•	Answer Remark :		
			The packing of Cargo manhole doors has gone		Link 2
			hard and need to be renewed. The vessel has		Link 3
			got the packing in spare.		LIIIK 3
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.26b - Tankers - Ballast tank	Grade - Yes	No	
•		openings	Answer Remark :		
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.26c - Tankers - Deck valves	Grade - Yes	No	
·		including stub pieces	Answer Remark :		
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.26d - Tankers - Ullage ports / vapor	Grade - Yes	No	
·		locks	Answer Remark :		
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.26e - Tankers - Level gauging	Grade - Yes	No	
•		systems	Answer Remark :		
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.26f - Tankers - PV valves / air vents /	Grade - Yes	No	
		Mast risers	Answer Remark :		
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.26g - Tankers - Deck Seal / PV	Grade - Yes	No	
		Breaker on IG line	Answer Remark :		
01.00 - Area/Item Inspected	01.02 - Part II - Decks	01.02.27 - Deck Lighting and Emergency	Grade - Yes	No	
·		Lighting	Answer Remark :		
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.01 - Internal Hull Structure - Fore	Grade - Yes	No	
·		peak store(s)	Answer Remark :		
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.02 - Internal Hull Structure - Paint	Grade - Yes	No	
·		room including its fixed fire extinguishing	Answer Remark :		
		system			
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.03 - Internal Hull Structure - Fore	Grade - Yes	No	
·		peak tank	Answer Remark :		
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.04 - Internal Hull Structure - Chain	Grade - Yes	No	
•		lockers and void spaces	Answer Remark :		

----- InnerException -----

The underlying connection was closed: An unexpected error occurred on a

The client and server cannot communicate, because they do not

Maritec Tanker Management Private Limited

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.05 - Internal Hull Structure - For'd	Grade - Yes	No	
or.oo modifican moposiou	or.oo rarem momarramonadaro	hydraulic room for mooring winches	Answer Remark :	110	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.06 - Internal Hull Structure - Cargo	Grade - Yes	No	
		tank No 1 C/P/S(includes insulation)	Answer Remark :		
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.07 - Internal Hull Structure - Cargo	Grade - Yes	No	
•		tank No 2 C/P/S(includes insulation)	Answer Remark :		
		,	RECENTLY DONE IN DRYDOCK 2S		
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.08 - Internal Hull Structure - Cargo	Grade - Yes	No	
•		tank No 3 C/P/S(includes insulation)	Answer Remark :		
		· ·	RECENTLY DONE IN DRYDOCK 3P, 3S		
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.09 - Internal Hull Structure - Cargo	Grade - Yes	No	
		tank No 4 C/P/S(includes insulation)	Answer Remark :		
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.10 - Internal Hull Structure - Cargo	Grade - Yes	No	
		tank No 5 C/P/S(includes insulation)	Answer Remark :		
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.11 - Internal Hull Structure - Cargo	Grade - Yes	No	
		tank No 6 C/P/S(includes insulation)	Answer Remark :		
			RECENTLY DONE IN DRYDOCK - 6S		
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.12 - Internal Hull Structure - Cargo	Grade - Yes	No	
		tank No 7 C/P/S(includes insulation)	Answer Remark :		
			RECENTLY DONE IN DRYDOCK- 7S		
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.13 - Internal Hull Structure - Cargo		No	
		tank No 8 C/P/S(includes insulation)			
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.14 - Internal Hull Structure - Cargo		No	
		tank No 9 C/P/S(includes insulation)			
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.15 - Internal Hull Structure - Water	Grade - Yes	No	
		ballast topside tanks	Answer Remark :		
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.16 - Internal Hull Structure - Water	Grade - No	No	
		ballast D.B. tanks	Answer Remark :		
			Some of the DB's are remaining to be		
			cosmetically upgraded		
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.17 - Internal Hull Structure - Slop	Grade - Yes	No	
24.00 A ///	04.00 D (III 1 1 1 1 1 1	tanks	Answer Remark :		
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.18 - Internal Hull Structure -	Grade - No	No	
		Butterworthing machines	Answer Remark :		
24.00	04.00 David III. Jasta are all I ladi Otara ataura	04.00.40	NA Na	NI=	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.19 - Internal Hull Structure - COW	Grade - No	No	
		system	Answer Remark :		
04.00 Amaz/ltama lmana - t l	04.02 Down III. Indown al I will China them.	04.02.20 Internal Hall Structure 12	NA Crada Vaa	NI-	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.20 - Internal Hull Structure - IG	Grade - Yes	No	
04.00 A was //tame Image = + = -!	04.02 Down III. Indown al I will China them.	system and valves	Answer Remark :	NI-	
01.00 - Area/Item Inspected	01.03 - Part III - Internal Hull Structure	01.03.21 - Internal Hull Structure - Deep	Grade - No	No	
		tanks outside E/R	Answer Remark :		

----- InnerException -----

The underlying connection was closed: An unexpected error occurred on a receive.

----- InnerException -----

The client and conver cannot communicate herause they do not noccess a

Maritec Tanker Management Private Limited

01.03 - Part III - Internal Hull Structure	01.03.22 - Internal Hull Structure -	Grade - No		
	0 1100122 111101110111011010101010	Grade - NO	No	
	Cofferdams outside E/R	Answer Remark :		
01.03 - Part III - Internal Hull Structure	01.03.23 - Internal Hull Structure - Pipe	Grade - Yes	No	
	tunnel	Answer Remark :		
01.03 - Part III - Internal Hull Structure	01.03.24 - Internal Hull Structure - Aft peak	Grade - No	No	
	stores	Answer Remark :		
		NA		
01.03 - Part III - Internal Hull Structure	01.03.25 - Internal Hull Structure - E/R	Grade - Yes	No	
	L.O. tanks	Answer Remark :		
01.03 - Part III - Internal Hull Structure	01.03.26 - Internal Hull Structure - E/R	Grade - No	No	
	D.B. tanks	Answer Remark :		
01.03 - Part III - Internal Hull Structure	01.03.27 - Internal Hull Structure - E/R	Grade - Yes	No	
	bunker tanks	Answer Remark :		
01.03 - Part III - Internal Hull Structure	01.03.28 - Internal Hull Structure -	Grade - Yes	No	
	Cofferdams inside E/R	Answer Remark :		
01.04 - Part IV - Mast Houses / Midship	01.04.01 - Mast Houses/ Midship Stores -	Grade - Yes	No	
Stores		Answer Remark :		
01.04 - Part IV - Mast Houses / Midship			No	
Stores				
01.04 - Part IV - Mast Houses / Midship			No	
Stores				
01.04 - Part IV - Mast Houses / Midship			No	
	Doors			
	01.04.05 - Mast Houses / Midship Stores -		No	Link 1
				Link 2
01.04 - Part IV - Mast Houses / Midship	01.04.06 - Mast Houses / Midship Stores -	Grade - Yes	No	
•	•			
			No	
			No	Link 1
•			110	Ziiiik i
0.0100	Troubb Rooping			
01 05 - Part V - Cargo Pump Room	01 05 01 - Cargo Pump Room -		No	
o 1.00 Tait v - Gargo Tamp 1.00m			110	
01 05 - Part V - Cargo Pump Room			No	
o 1.00 - 1 art v - Cargo i dilip i toolii			NO	
		ANDWOLLTOINAIN.		
01 05 - Part V - Cargo Pump Poom		Grade - Ves	No	
01.00 - Fait v - Gargo Fullip Room			INU	
	01.03 - Part III - Internal Hull Structure 01.04 - Part IV - Mast Houses / Midship Stores 01.04 - Part IV - Mast Houses / Midship Stores 01.04 - Part IV - Mast Houses / Midship Stores 01.04 - Part IV - Mast Houses / Midship Stores 01.04 - Part IV - Mast Houses / Midship Stores 01.04 - Part IV - Mast Houses / Midship Stores 01.04 - Part IV - Mast Houses / Midship Stores 01.04 - Part IV - Mast Houses / Midship Stores	01.03 - Part III - Internal Hull Structure 01.03 - Part IV - Mast Houses / Midship 01.04 - Part IV - Mast Houses / Midship 01.05 - Part IV - Mast Houses / Midship 01.05 - Part IV - Cargo Pump Room 01.05 - Part IV - Cargo Pump Room	O1.03 - Part III - Internal Hull Structure	01.03 - Part III - Internal Hull Structure

----- InnerException -----

The underlying connection was closed: An unexpected error occurred on a receive.

----- InnerException -----

The client and conver cannot communicate herause they do not noscess a

Maritec Tanker Management Private Limited

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.04 - Cargo Pump Room - Vacuum stripping system	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.05 - Cargo Pump Room - Pipe	Grade - No	No	Link 1
		lines/Insulations	Answer Remark : Ballast water lines need to be painted. Nut/Bolts		Link 2
			to be derusted and U clamps drusting to be done.		Link 3
					Link 4
					Link 5
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.06 - Cargo Pump Room - Bilges	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.07 - Cargo Pump Room - Ventilation/Bottom Flap Operation from outside P/P Room	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.08 - Cargo Pump Room - Ladders, Platforms and gratings	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.09 - Cargo Pump Room - Bilge Alarm(s)	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.10 - Cargo Pump Room - Butterworth heater		No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.11 - Cargo Pump Room - Lighting	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.12 - Cargo Pump Room - Hydraulic and pneumatic valves and pipelines in p/p room	Grade - Yes	No	
01.00 - Area/Item Inspected	01.05 - Part V - Cargo Pump Room	01.05.13 - Cargo Pump Room - Gas detection system	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation Spaces	01.06.01 - Accommodation Spaces - Companionways on open decks	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.02 - Accommodation Spaces - Vent	Grade - No	No	Link 1
	Spaces	flaps - natural and forced	Answer Remark : Accommodation AC inlet on the Stbd Aft of accommodation is wasted. New mesh supports to be fabricated and mesh renewed.		Link 2

----- InnerException -----

The underlying connection was closed: An unexpected error occurred on a receive.

----- InnerException -----

The client and conver cannot communicate herause they do not noccess a

Maritec Tanker Management Private Limited

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.03 - Accommodation Spaces -	Grade - No	No	Link 1
	Spaces	Accommodation decks	Answer Remark :		Link 2
			Accommodation decks cosmetic appearance to		
			maintain.		Link 3
					Link 4
					Link 5
					Link 6
					Link 7
					LINK /
					Link 8
					Link 9
					Link 10
					Link 11
					Limb 40
					Link 12
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.04 - Accommodation Spaces - Doors		No	
	Spaces	- Watertight / Weather tight	Answer Remark :		
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.05 - Accommodation Spaces - Deck		No	
	Spaces	lighting and cable fitting	Answer Remark :		
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.06 - Accommodation Spaces -	Grade - Yes	No	
	Spaces	Railings	Answer Remark :		
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.07 - Accommodation Spaces -	Grade - Yes	No	
100 1 11	Spaces	Companionways inside accommodation	Answer Remark :		
1.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.08 - Accommodation Spaces -	Grade - No	No	
	Spaces	Alleyways	Answer Remark :		
			Crew using alleyways for drying clothes. Same		
04.00 A	04.00 Dart VIII. A a a a sur a dation	04.00.00	practice to be stopped.	N1-	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.09 - Accommodation Spaces -	Grade - Yes	No	
04.00 A === //ta=== l===== ata d	Spaces	Lighting inside alleyways	Answer Remark :	NI-	
1.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.10 - Accommodation Spaces -	Grade - Yes	No	
04.00 A === //ta == l === = ata d	Spaces 01.06 - Part VI - Accommodation	Galley	Answer Remark : Grade - Yes	NI-	
01.00 - Area/Item Inspected		01.06.11 - Accommodation Spaces - Pantries	Answer Remark :	No	
01.00 Area/Itam Inchested	Spaces 01.06 - Part VI - Accommodation	01.06.12 - Accommodation Spaces -	Grade - Yes	No	
01.00 - Area/Item Inspected	Spaces	Provision rooms	Answer Remark :	INO	
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.13 - Accommodation Spaces -	Grade - Yes	No	
71.00 - Area/item inspected				INO	
	Spaces	Fridge rooms	Answer Remark :		

----- InnerException -----

The underlying connection was closed: An unexpected error occurred on a

The client and server cannot communicate, because they do not

Maritec Tanker Management Private Limited

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.14 - Accommodation Spaces -	Grade - Yes	No	
	Spaces	Laundries and dry rooms	Answer Remark :		
1.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.15 - Accommodation Spaces -	Grade - Yes	No	
	Spaces	Hobby room	Answer Remark :		
			NA		
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation			No	
	Spaces	Wash rooms	Answer Remark :		
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	•		No	
	Spaces	change rooms	Answer Remark :		
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.18 - Accommodation Spaces - Crew		No	
	Spaces	cabins	Answer Remark :		
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.19 - Accommodation Spaces -	Grade - Yes	No	
	Spaces	Officers cabins	Answer Remark :		
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.20 - Accommodation Spaces -	Grade - Yes	No	
	Spaces	Officers Mess room	Answer Remark :		
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.21 - Accommodation Spaces -	Grade - Yes	No	
	Spaces	Officers lounge / smoke room	Answer Remark :		
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.22 - Accommodation Spaces - Crew		No	
	Spaces	mess room	Answer Remark :		
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.23 - Accommodation Spaces - Crew	Grade - Yes	No	
	Spaces	lounge / smoke room	Answer Remark :		
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.24 - Accommodation Spaces -	Grade - Yes	No	
	Spaces	Welfare equipment	Answer Remark :		
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.25 - Accommodation Spaces - Deck		No	
	Spaces	office / Cargo control room and its	Answer Remark :		
		equipments			
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.26 - Accommodation Spaces -	Grade - Yes	No	
	Spaces	Conference room	Answer Remark :		
			ship office		
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.27 - Accommodation Spaces -	Grade - Yes	No	Link 1
	Spaces	Engineers office	Answer Remark :		
			NA		Link 2
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.28 - Accommodation Spaces - Store	Grade - No	No	Link 1
7 i da/itani mapadad	Spaces	rooms and lockers	Answer Remark :	110	Liiik
	Οράουσ -	rooms and lookers	The safety store needs to be arranged properly		Link 2
			The salety store needs to be alranged properly		
					Link 3
					Link 4
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.29 - Accommodation Spaces - Cable		No	
	Spaces	ducts	Answer Remark :		

----- InnerException -----

The underlying connection was closed: An unexpected error occurred on a receive.

----- InnerException -----

The client and conver cannot communicate herause they do not noscess a

Maritec Tanker Management Private Limited

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.06 - Part VI - Accommodation	01.06.30 - Accommodation Spaces -	Grade - Yes	No	
	Spaces	Garbage bins	Answer Remark :		
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.01 - Navigation Bridge - General	Grade - Yes	No	
		maintenance and house keeping	Answer Remark :		
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.02 - Navigation Bridge - Chart room	Grade - Yes	No	
			Answer Remark :		
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.03 - Navigation Bridge - Battery	Grade - Yes	No	
		room	Answer Remark :		
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.04 - Navigation Bridge - Navigation	Grade - Yes	No	
		light masts and fittings	Answer Remark :		
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.05 - Navigation Bridge - Magnetic	Grade - No	No	Link 1
		Compass - standard / gyro and repeaters	Answer Remark :		1:10
			Azimuth Sensor of magnetic compass defective.		Link 2
			Same to be replaced with new spares.		
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.06 - Navigation Bridge - Auto Pilot	Grade - Yes	No	
			Answer Remark :		
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.07 - Navigation Bridge - Helm	Grade - Yes	No	
		indicators - inside wheelhouse and on	Answer Remark :		
		bridge wings			
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.08 - Navigation Bridge -	Grade - Yes	No	
		Tachometers - inside wheelhouse and on	Answer Remark :		
		bridge wings			
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.09 - Navigation Bridge - Deck IG	Grade - Yes	No	
		manometer	Answer Remark :		
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.10 - Navigation Bridge - Radars and	Grade - Yes	No	
		ARPA	Answer Remark :		
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.11 - Navigation Bridge - VHF	Grade - Yes	No	
·	_	-	Answer Remark :		
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.12 - Navigation Bridge - Echo	Grade - Yes	No	
·	_	sounder	Answer Remark :		
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.13 - Navigation Bridge - AIS	Grade - Yes	No	
·			Answer Remark :		
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.14 - Navigation Bridge - SSAS	Grade - Yes	No	
·			Answer Remark :		
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.15 - Navigation Bridge - BNWAS	Grade - Yes	No	
·	5		Answer Remark :		
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.16 - Navigation Bridge - Voyage data	Grade - Yes	No	
·	5	recorder	Answer Remark :		
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.17 - Navigation Bridge - Speed log	Grade - Yes	No	
•	5 0		Answer Remark :		
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.18 - Navigation Bridge - GPS /	Grade - Yes	No	
•	3 0	Satellite Navigator	Answer Remark :		

----- InnerException -----

The underlying connection was closed: An unexpected error occurred on a receive.

----- InnerException -----

The client and conver cannot communicate herause they do not noccess a

Maritec Tanker Management Private Limited

Chapter	Category	Question	Answer Details	Is Critical Lin
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.19 - Navigation Bridge -	Grade - Yes	No
		Chronometer	Answer Remark :	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.20 - Navigation Bridge - Barometer	Grade - Yes	No
			Answer Remark :	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.21 - Navigation Bridge - Sextants	Grade - Yes	No
•			Answer Remark :	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.22 - Navigation Bridge - Binoculars	Grade - Yes	No
·	5	0 0	Answer Remark :	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.23 - Navigation Bridge - Aldis lamp	Grade - Yes	No
,	3 3	3 3	Answer Remark :	
1.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.24 - Navigation Bridge - Flags	Grade - Yes	No
	g	• · · · · · · · · · · · · · · · · · · ·	Answer Remark :	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.25 - Navigation Bridge - Charts and	Grade - Yes	No
, 1.00	onor rantin manganen zhage	status of correction	Answer Remark :	
11.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.26 - Navigation Bridge - ECDIS	Grade - Yes	No
7.100 7.10d/Hom Hopeotod	That I are the Havigation Bridge	onorizo mangation bilago zobio	Answer Remark :	110
11.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.27 - Navigation Bridge - Nautical	Grade - Yes	No
7 Tod/Itom mopoded	01.07 Tare VII Havigation Bridge	Publications	Answer Remark :	140
1.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.28 - Navigation Bridge - Notices to	Grade - Yes	No
1.00 - Arca/Item mapecied	01.07 - Fait VIII - Navigation Bridge	Mariners	Answer Remark :	140
1.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.29 - Navigation Bridge - Technical	Grade - Yes	No
71.00 - 7 trea/item mapeoted	01.07 - 1 dit vii - Navigation Briage	Library	Answer Remark :	140
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.30 - Navigation Bridge - Radio room		No
71:00 - Area/Item mapeeted	01.07 - Fait VII - Navigation Bridge	01.07.00 - Navigation Bridge - Nadio 100m	Answer Remark :	140
			NA	
1.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.31 - Navigation Bridge - Main	Grade - Yes	No
71.00 - Area/item mspecied	01.07 - Falt VII - Navigation Bridge	transmitter / Main Receiver	Answer Remark :	NO
1.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.32 - Navigation Bridge - Emergency		No
1.00 - Area/item inspected	01.07 - Part VII - Navigation Bridge	transmitter / Emergency Receiver	Answer Remark :	INO
1.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.33 - Navigation Bridge - GMDSS	Grade - Yes	No
1.00 - Area/item inspected	01.07 - Part VII - Navigation Bridge	Walkie Talkies	Answer Remark :	INO
11.00 Anna/Itama Imama ata d	04.07 David VIII. Navigation Deidan			NI-
1.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.34 - Navigation Bridge - GMDSS	Grade - Yes	No
14 00 A ///	04.07 B ()/II N : (' B : I	VHF DSC (Operation)	Answer Remark :	
11.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.35 - Navigation Bridge - GMDSS	Grade - Yes	No
		batteries	Answer Remark :	
1.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.36 - Navigation Bridge - Satcom /	Grade - Yes	No
		GMDSS terminal	Answer Remark :	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.37 - Navigation Bridge - Computer /	Grade - Yes	No
		UPS / Stabilizer	Answer Remark :	
01.00 - Area/Item Inspected	01.07 - Part VII - Navigation Bridge	01.07.38 - Navigation Bridge - Hospital	Grade - Yes	No
		alarm	Answer Remark :	

----- InnerException -----

The underlying connection was closed: An unexpected error occurred on a

The client and server cannot communicate, because they do not

Maritec Tanker Management Private Limited

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.01 - Engine Room - Housekeeping	Grade - No	No	Link 1
		and general maintenance	Answer Remark :		Link 2
			Hygiene needs to be maintained . Very dirty cups		LINK 2
			and extremely dirty Tea/coffee area in ECR.		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02a - Engine Room - Main engine -	Grade - No	No	Link 1
		Turbo charger	Answer Remark :		
			ME T/C needs to be painted with Aluminium		
			paint.		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02b - Engine Room - Main engine -	Grade - Yes	No	
		Control stand	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02c - Engine Room - Main engine -	Grade - Yes	No	
		Thrust block	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02d - Engine Room - Main engine -	Grade - Yes	No	
		Shaft bearings	Answer Remark :		
			NA		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02e - Engine Room - Main engine -	Grade - Yes	No	
		Shaft tunnel	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02f - Engine Room - Main engine -	Grade - Yes	No	
		Turning gear system	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02g - Engine Room - Main engine -	Grade - Yes	No	
		Crankcase doors	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02h - Engine Room - Main engine -	Grade - Yes	No	
		Under Piston area	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02i - Engine Room - Main engine -	Grade - Yes	No	
		Scavenge space	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02j - Engine Room - Main engine -	Grade - Yes	No	
		Exhaust manifold	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02k - Engine Room - Main engine -	Grade - Yes	No	
		Fuel oil booster pump	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02l - Engine Room - Main engine -	Grade - Yes	No	
		Fuel oil heating system	Answer Remark :		
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02m - Engine Room - Main engine -		No	
		L.O.pumps	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02n - Engine Room - Main engine -	Grade - Yes	No	
		Alarms and Trips	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02o - Engine Room - Main engine -	Grade - Yes	No	
		Air cooler manometers	Answer Remark :		
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02p - Engine Room - Main engine -	Grade - Yes	No	
-		Uptake manometers	Answer Remark :		
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02q - Engine Room - Main engine -	Grade - Yes	No	
•	-	Sheathing on HP fuel pipes	Answer Remark :		

----- InnerException -----

The underlying connection was closed: An unexpected error occurred on a receive.

----- InnerException -----

The client and conver cannot communicate, because they do not noccess a

Maritec Tanker Management Private Limited

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02r - Engine Room - Main engine -	Grade - Yes	No	
		Spark arrestors on exh. uptakes	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02s - Engine Room - Main engine -	Grade - Yes	No	
·	-	Exh. boiler gas passage drains clear	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.02t - Engine Room - Main engine -	Grade - Yes	No	
·	•	T/C gas passage drains clear	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.03 - Engine Room - Main S.W	Grade - No	No	Link 1
•	•	pumps	Answer Remark :		
			Main Sea water pumps leaking from mechanical		
			seal. To be overhauled.		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.04 - Engine Room - Cooling F.W	Grade - Yes	No	
•	G	pumps	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.05 - Engine Room - Fire pump	Grade - Yes	No	
,	3	y 1 1	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.06 - Engine Room - Bilge pump	Grade - Yes	No	
	g		Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.07 - Engine Room - General Service		No	
	g	pump	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.08 - Engine Room - Ballast pump	Grade - Yes	No	
7 o	2 1.00	iologico Eligino i teem Edinact painip	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.09 - Engine Room - Bilge & floor	Grade - Yes	No	
, , ,	2 1.00	plates (safety aspects and cleanliness)	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.10 - Engine Room - Fuel oil transfer	Grade - Yes	No	
	g	pump	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.11 - Engine Room - L.O transfer	Grade - Yes	No	
	g	pump	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.12 - Engine Room - Sludge pump	Grade - Yes	No	
	2 1.00	. o. oog too o.a.ago pap	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.13 - Engine Room - Domestic F.W	Grade - Yes	No	
Tion / wearten mepocied	ones ran un Engine reem	pump	Answer Remark :	110	
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.14 - Engine Room - Sanitary water	Grade - Yes	No	
1.00 / trou/itom mopootou	oned rait viii Engino reem	pump	Answer Remark :	110	
11.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.15 - Engine Room - Fridge cooling	Grade - Yes	No	
1.00 - / (rea/item mapeolea	01.00 - 1 art viii - Engine Room	pump	Answer Remark :	110	
11.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.16 - Engine Room - A/C S.W pump	Grade - Yes	No	
1.00 - Arca/ItcIII III3pcctcu	01.00 -1 art viii - Engine Room	10.00.10 - Engine Room - 7/0 0.W pamp	Answer Remark :	140	
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.17 - Engine Room - Harbor service	Grade - Yes	No	
71.00 - Area/Rem mspecied	01.00 - Fait VIII - Eligille Roolli	•	Answer Remark :	INU	
		pump	NA		
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.18 - Engine Room - All S.W. valves	Grade - Yes	No	
71.00 - Area/Reili ilispected	01.00 - Fait VIII - Eligille Roolli	10.00.10 - Engine Room - All 3.W. Valves	Answer Remark :	INU	

----- InnerException -----

The underlying connection was closed: An unexpected error occurred on a receive.

----- InnerException -----

The client and conver cannot communicate herause they do not noscess a

Maritec Tanker Management Private Limited

Chapter	Category	Question	Answer Details	Is Critical Link
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.19 - Engine Room - Tank top	Grade - Yes Answer Remark :	No
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.20 - Engine Room - Piping - general and in bilge areas	Grade - Yes Answer Remark :	No
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.21 - Engine Room - H.O Purifier	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.22 - Engine Room - D.O Purifier	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.23 - Engine Room - L.O Purifier	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.24 - Engine Room - Main air compressor	Grade - Yes Answer Remark :	No
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.25 - Engine Room - Top up compressor	Allower Remark .	No
11.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.26 - Engine Room - Emergency air compressor	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.27 - Engine Room - Air bottles, Control air dryers	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.28 - Engine Room - M/E coolers	Grade - Yes Answer Remark :	No
11.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.29 - Engine Room - A/E coolers	Grade - Yes Answer Remark :	No
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.30 - Engine Room - Fuel heater & Lagging on hot fuel pipes	Grade - Yes Answer Remark :	No
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.31 - Engine Room - Metal sheathing on H.P fuel pipes		No
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.32 - Engine Room - Viscometers	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.33 - Engine Room - Hydrophore tanks	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34a - Engine Room - Aux. Engines - General condition and maintenance		No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34b - Engine Room - Aux. Engines - Turbo charger		No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34c - Engine Room - Aux. Engines - Alarms and trips		No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34d - Engine Room - Aux. Engines - Crankcase doors		No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34e - Engine Room - Aux. Engines - Pressure and Temperature gauges		No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34f - Engine Room - Aux. Engines - Nozzle cooling pump	, alonoi romant.	No

----- InnerException -----

The underlying connection was closed: An unexpected error occurred on a

The client and server cannot communicate, because they do not

Maritec Tanker Management Private Limited

Chapter	Category	Question	Answer Details	Is Critical Lin
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	Attached F.W. pump	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34h - Engine Room - Aux. Engines - Nozzle cooling pump		No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34i - Engine Room - Aux. Engines - Governor	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34j - Engine Room - Aux. Engines - Exh. pipe lagging / metal sheathing	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34k - Engine Room - Aux. Engines - F.W. / L.O. Coolers		No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34I - Engine Room - Aux. Engines - Floor plates under A/Es clean & oil free?	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34m - Engine Room - Aux. Engines - m. Deck-head & pipes / cables above A/Es clean and oil free?	Grade - Yes	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.34n - Engine Room - Aux. Engines - n. Auto temperature controllers L.O. / F.W. temp		No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.35 - Engine Room - Alternators	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.36 - Engine Room - Motors / starters	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.37 - Engine Room - Main switchboard	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.38 - Engine Room - Emergency switchboard	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.39 - Engine Room - Cable trays	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.40 - Engine Room - Emergency Generator / Batteries	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.41 - Engine Room - Fridge compressor	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.42 - Engine Room - Condensers / coolers	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.43 - Engine Room - Thermostatic valves		No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.44 - Engine Room - Coils / fans	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.45 - Engine Room - E/R blowers	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.46 - Engine Room - Engine Control	Grade - Yes	No

----- InnerException -----

The underlying connection was closed: An unexpected error occurred on a receive.

----- InnerException -----

The client and conver cannot communicate thereto they do not noccess a

Maritec Tanker Management Private Limited

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.47 - Engine Room - F.W generator	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.48 - Engine Room - Oily water	Grade - Yes	No	
		separator	Answer Remark :		
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.49 - Engine Room - Sewage Plant	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.50 - Engine Room - Incinerator	Grade - Yes	No	
71.00 7 il dantem mopolica	on.oo ran viii Engino Noom	10.00.00 Engine Room momerates	Answer Remark :	140	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51a - Engine Room - Boilers (steam	Grade - Yes	No	
·	, and the second	and thermal oil) - Condition and general maintenance	Answer Remark :		
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room		Grade - Yes	No	
·	•	and thermal oil) - Feed water pumps	Answer Remark :		
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51c - Engine Room - Boilers (steam	Grade - Yes	No	
·	•	and thermal oil) - Circulation pump `	Answer Remark :		
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room			No	
		and thermal oil) - Safety valve	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room			No	
		and thermal oil) - Gauge glass	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51f - Engine Room - Boilers (steam		No	
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room			No	
		and thermal oil) - F.D. fan	Answer Remark :		
11.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room		Grade - Yes	No	
		and thermal oil) - Boiler uptake lagging	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51i - Engine Room - Boilers (steam	Grade - Yes	No	
		and thermal oil) - All temperature and pressure gauges	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51j - Engine Room - Boilers (steam	Grade - Yes	No	
		and thermal oil) - F.O. pump	Answer Remark :		
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51k - Engine Room - Boilers (steam	Grade - Yes	No	
		and thermal oil) - F.O. heater	Answer Remark :		
11.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51I - Engine Room - Boilers (steam	Grade - Yes	No	
		and thermal oil) - Lagging on hot fuel oil	Answer Remark :		
		and Heating steam pipes			
11.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.51m - Engine Room - Boilers (steam		No	
		and thermal oil) - Steam dump valve and	Answer Remark :		
		other steam valves			
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room			No	
		and thermal oil) - Warning notices and	Answer Remark :		
		operating instructions			

----- InnerException -----

The underlying connection was closed: An unexpected error occurred on a

The client and server cannot communicate, because they do not

Maritec Tanker Management Private Limited

Chapter	Category	Question	Answer Details	Is Critical Link
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.52a - Engine Room - IG system - IG generator	Answer Remark : NA	No
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.52b - Engine Room - IG system - IG control panel and control system	Grade - Yes Answer Remark :	No
11.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.52c - Engine Room - IG system - Pneumatic system	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.52d - Engine Room - IG system - IG blower	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.52e - Engine Room - IG system - Scrubber unit	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.52f - Engine Room - IG system - Oxygen analyzer	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.53 - Engine Room - Soot blower	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.54 - Engine Room - Exhaust boiler	Grade - Yes Answer Remark :	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55a - Engine Room - COP turbines - Condition and general maintenance		No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55b - Engine Room - COP turbines - Alarms and trips	Grade - Yes Answer Remark : NA	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55c - Engine Room - COP turbines - governor	Grade - Yes Answer Remark : NA	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55d - Engine Room - COP turbines - L.O. pump	Grade - Yes Answer Remark : NA	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55e - Engine Room - COP turbines - L.O. cooler	Grade - Yes Answer Remark : NA	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55f - Engine Room - COP turbines - Control panel	Grade - Yes Answer Remark : NA	No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55g - Engine Room - COP turbines - Tachometer		No
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.55h - Engine Room - COP turbines - Local temp and pressure gauges	Grade - Yes Answer Remark : NA	No

----- InnerException -----

The underlying connection was closed: An unexpected error occurred on a

The client and server cannot communicate, because they do not up

Maritec Tanker Management Private Limited

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.56 - Engine Room - Vacuum condenser	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.57 - Engine Room - Condenser S.W. pump	Grade - Yes Answer Remark : NA	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.58 - Engine Room - Hot well	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.59 - Engine Room - CO2 room	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.60 - Engine Room - Quick closing valves	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.61 - Engine Room - Remote switches and cut-offs	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.62 - Engine Room - Sky light	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.63 - Engine Room - Blower flaps	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.64 - Engine Room - Steering flat	Grade - Yes Answer Remark :	No	
11.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.65 - Engine Room - Storage of chemicals	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.66 - Engine Room - Workshop	Grade - Yes Answer Remark: 10.08.66 Please tidy up the workshop. All tools to be kept in their places. Rags should not be lying anywhere in the Engine room. Paint the area as required.	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.67 - Engine Room - E/R crane	Grade - Yes Answer Remark :	No	
1.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.68 - Engine Room - Stores	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.69 - Engine Room - Spares	Grade - No Answer Remark : To be checked and Rob to be matched with JOT	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.70 - Engine Room - Tools / instruments	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.08 - Part VIII - Engine Room	10.08.71 - Engine Room - LO and water treatment test kits	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.01 - Record Keeping - Deck Log Book	Grade - Yes Answer Remark :	No	

----- InnerException -----

The underlying connection was closed: An unexpected error occurred on a receive.

----- InnerException -----

The client and conver cannot communicate herause they do not noscess a

Maritec Tanker Management Private Limited

Chapter	Category	Question	Answer Details	Is Critical	Link
1.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.02 - Record Keeping - Official Log	Grade - Yes	No	
		Book	Answer Remark :		
1.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.03 - Record Keeping - Night Order	Grade - Yes	No	
		Book	Answer Remark :		
1.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.04 - Record Keeping - Movement	Grade - Yes	No	
		(Bell) Book	Answer Remark :		
1.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.05 - Record Keeping - Sounding	Grade - Yes	No	
		Book	Answer Remark :		
1.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.06 - Record Keeping - Compass	Grade - Yes	No	
		error Book	Answer Remark :		
1.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.07 - Record Keeping - Chronometer	Grade - Yes	No	
		Log	Answer Remark :		
1.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.08 - Record Keeping - Radio Log	Grade - Yes	No	
			Answer Remark :		
1.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.09 - Record Keeping - Radar Log	Grade - Yes	No	
·	· -		Answer Remark :		
1.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.10 - Record Keeping - Chart	Grade - Yes	No	
·	· -	correction folio	Answer Remark :		
1.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.11 - Record Keeping - Garbage Log	Grade - Yes	No	
·	1 0		Answer Remark :		
1.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.12 - Record Keeping - Videotel /	Grade - Yes	No	
·	1 0	Training Log	Answer Remark :		
1.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.13 - Record Keeping - Calibration	Grade - Yes	No	
·	1 0	Log	Answer Remark :		
1.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.14 - Record Keeping - Stores	Grade - No	No	
		inventory (deck and saloon)	Answer Remark :		
		,	Inventory in JOT to be updated prior sending		
			requisitions.		
1.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.15 - Record Keeping - Spare Part	Grade - Yes	No	
		Inventory (Deck)	Answer Remark :		
1.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.16 - Record Keeping - Planned	Grade - Yes	No	
		Maintenance Records(Deck, Radio, Safety			
		Equipment)	, ii. 51, 51, 13, 11, 11, 11, 11, 11, 11, 11, 11, 1		
1.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.17 - Record Keeping - Masters Filing	Grade - Yes	No	
	cities i air into i tesera i tesering	System	Answer Remark :		
1.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.18 - Record Keeping - Chief	Grade - Yes	No	
	1 a	Engineers Filing System	Answer Remark :		
1.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.19 - Record Keeping - E/R Log Book		No	
/ wod/tom mopolica	5 1.05 Tartix Rooma Rooping	10.00.10 Procedure recoping Lift Log Book	Answer Remark :	110	
			E/R logbook is being filled up by Oilers. Same to		
			be done by watckeeping Engineers.		
			be done by watercoping Engineers.		

----- InnerException -----

The underlying connection was closed: An unexpected error occurred on a

The client and server cannot communicate, because they do not u

Maritec Tanker Management Private Limited

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.20 - Record Keeping - Oil Record	Grade - Yes	No	
		Book	Answer Remark :		
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.21 - Record Keeping - E/R tank	Grade - Yes	No	
		sounding book	Answer Remark :		
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.22 - Record Keeping - Survey	Grade - Yes	No	
		records / Quarterly listing	Answer Remark :		
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.23 - Record Keeping - Spare Part	Grade - Yes	No	
		Inventory (E/R)	Answer Remark :		
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.24 - Record Keeping - Planned	Grade - Yes	No	
		Maintenance Records (Main, Aux. and	Answer Remark :		
		Electrical machinery)			
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.25 - Record Keeping - Ships	Grade - Yes	No	
		drawings and manuals	Answer Remark :		
01.00 - Area/Item Inspected	01.09 - Part IX - Record Keeping	10.09.26 - Record Keeping - Ship Security		No	
		Records			
01.00 - Area/Item Inspected	01.10 - Part X - Certificates And	10.10.01 - Certificates and Approvals -	Grade - Yes	No	
-	Approvals	Statutory certificates as per Form D-13	Answer Remark :		
01.00 - Area/Item Inspected	01.10 - Part X - Certificates And	10.10.02 - Certificates and Approvals -	Grade - Yes	No	
	Approvals	Type approval Certificates for L/Jackets,	Answer Remark :		
		L/Buoys, Pyrotechnics, Navigation Lights,			
		Sound Signal equipment, shapes,			
		fireman's outfits, fire detection system,			
		alarms, ODME, ODMCS, Sewage plant			
01.00 - Area/Item Inspected	01.10 - Part X - Certificates And	10.10.03 - Certificates and Approvals -	Grade - Yes	No	
	Approvals	Wires and Ropes Test Certificates	Answer Remark :		
01.00 - Area/Item Inspected	01.10 - Part X - Certificates And	10.10.04 - Certificates and Approvals -	Grade - Yes	No	
	Approvals	Chain Register	Answer Remark :		
01.00 - Area/Item Inspected	01.10 - Part X - Certificates And	10.10.05 - Certificates and Approvals - Life	Grade - Yes	No	
	Approvals	raft Certificate	Answer Remark :		
01.00 - Area/Item Inspected	01.10 - Part X - Certificates And	10.10.06 - Certificates and Approvals -	Grade - Yes	No	
•	Approvals	Administration approved LSA, LSS and	Answer Remark :		
	• •	FFA plans			
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And	10.11.01 - Safety Equipment and Alarms -	Grade - Yes	No	
	Alarms	General Alarm	Answer Remark :		
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And	10.11.02 - Safety Equipment and Alarms -	Grade - Yes	No	
	Alarms	Fire detection system	Answer Remark :		
		(Accommodation/E.R/Cargo holds)			
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And	10.11.03 - Safety Equipment and Alarms -	Grade - Yes	No	
	Alarms	Hospital Bell	Answer Remark :		
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And	10.11.04 - Safety Equipment and Alarms -		No	
VI.UU - Area/Hem Inspected					

----- InnerException -----

The underlying connection was closed: An unexpected error occurred on a receive.

----- InnerException -----

The client and conver cannot communicate herause they do not nossess a

Maritec Tanker Management Private Limited

Chapter	Category	Question	Answer Details	Is Critical Link
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And	10.11.05 - Safety Equipment and Alarms -		No
·	Alarms	Fridge room alarm	Answer Remark :	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And	10.11.06 - Safety Equipment and Alarms -	Grade - Yes	No
	Alarms	E/R Bilge High level alarms	Answer Remark :	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And	10.11.07 - Safety Equipment and Alarms -	Grade - Yes	No
	Alarms	CO2 / Halon release alarm	Answer Remark :	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And	10.11.08 - Safety Equipment and Alarms -	Grade - Yes	No
	Alarms	Vent fans flaps / funnel flaps / Remote	Answer Remark :	
		closing flaps		
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And	10.11.09 - Safety Equipment and Alarms -	Grade - Yes	No
	Alarms	Fixed foam system	Answer Remark :	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And	10.11.10 - Safety Equipment and Alarms -	Grade - Yes	No
	Alarms	Portable foam system	Answer Remark :	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And	10.11.11 - Safety Equipment and Alarms -	Grade - Yes	No
-	Alarms	Steam smothering	Answer Remark :	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And	10.11.12 - Safety Equipment and Alarms -	Grade - Yes	No
-	Alarms	Inert gas system	Answer Remark :	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And	10.11.13 - Safety Equipment and Alarms -	Grade - Yes	No
•	Alarms	Sprinkler system	Answer Remark :	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And	10.11.14 - Safety Equipment and Alarms -	Grade - Yes	No
	Alarms	Fire mains / hydrants	Answer Remark :	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And	10.11.15 - Safety Equipment and Alarms -	Grade - Yes	No
·	Alarms	Hoses / nozzles	Answer Remark :	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And	10.11.16 - Safety Equipment and Alarms -	Grade - Yes	No
·	Alarms	Pollution Locker and equipments	Answer Remark :	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And	10.11.17 - Safety Equipment and Alarms -	Grade - Yes	No
	Alarms	Emergency fire pump	Answer Remark :	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And	10.11.18 - Safety Equipment and Alarms -		No
·	Alarms	Emergency generator	Answer Remark :	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And	10.11.19 - Safety Equipment and Alarms -		No
·	Alarms	Emergency lights	Answer Remark :	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And	10.11.20 - Safety Equipment and Alarms -		No
	Alarms	Life boat operation	Answer Remark :	
01.00 - Area/Item Inspected		10.11.21 - Safety Equipment and Alarms -		No
	Alarms	Life boat equipment	Answer Remark :	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And	10.11.22 - Safety Equipment and Alarms -		No
, , , , , , , , , , , , , , , , , , , ,	Alarms	Life boat engines	Answer Remark :	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And	10.11.23 - Safety Equipment and Alarms -		No
	Alarms	Extinguishers - Foam, Water, DCP, CO2	Answer Remark :	-
01.00 - Area/Item Inspected		10.11.24 - Safety Equipment and Alarms -		No
	Alarms	Tankscope, Explosimeter, O2 analyzer and		-
		Toxic gas detector		

----- InnerException -----

The underlying connection was closed: An unexpected error occurred on a receive.

----- InnerException -----

The client and conver cannot communicate herause they do not noccess a

Maritec Tanker Management Private Limited

Chapter	Category	Question	Answer Details	Is Critical	Link
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.25 - Safety Equipment and Alarms - Breathalyzer	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.26 - Safety Equipment and Alarms - CABA, Resuscitation equipment	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.27 - Safety Equipment and Alarms - Fireman's outfit with accessories	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.11 - Part XI - Safety Equipment And Alarms	10.11.28 - Safety Equipment and Alarms - Emergency Towing System	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.12 - Part XII - Environmental	10.12.01 - Environmental - Ballast water management	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.12 - Part XII - Environmental	10.12.02 - Environmental - Garbage management	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.12 - Part XII - Environmental	10.12.03 - Environmental - Ship Energy efficiency plan	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.12 - Part XII - Environmental	10.12.04 - Environmental - Safety Meeting conducted with entire crew by Superintendent	Grade - Yes Answer Remark : Not conducted with the entire ship's crew but discussed with Department heads and crew representatives.	No	
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.01 - Security - Ship Security Records	·	No	
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.02 - Security - Security Equipments	Grade - Yes Answer Remark :	No	
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.03 - Security - Security Communications and SSAS		No	
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.04 - Security - Vessel Hardening		No	
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.05 - Security - Security Charts, Publications and Guidance		No	
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.06 - Security - Cyber Security incl. Access to IT/OT Terminals, Workstation Security etc.		No	
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.07 - Security - Cyber Response Plan		No	
01.00 - Area/Item Inspected	01.13 - Part XIII - Security	10.13.08 - Security - Personal Devices usage		No	