Maritec Tanker Management Private Limited

Non Conformance Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Saint James LG	Defect ID : 403	NCR # : 17/2024	Is NCR ? : Yes

Defect Details

During RINA inspection it has been noted that Stbd hose handling crane is out of service . To be permanently repaired and tested

Requisition Code :

Categories

Primary :	Dk Machinery	Inspector - Internal :		Vessel Dept :	Deck
Secondary :	Deck Cranes (Incldg. Provision)	Inspector External :		Office Dept :	Technical
		Inspection Date :			

Applicable Dates

Date Raised : 28-Mar-2024	ETC : 31-May-2024	Date Completed :

Other Details

Priority : Urgent Defect deferred to DD	Assigned By : Vessel	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

Causes

General wear & tier.

Corrective Action

Repair team is expected to board the vessel at her next call to Trinidad for carrying out required repairs.

Preventive Action

All deck cranes to be maintained in good working conditions all the time. Ensure a proper PMS routines to be carried out for deck cranes.

CONTRIBUTING FACTORS

Descriptions

Machinery / Equipment Damage

Root Causes- Job Factor

Excessive Wear and Tear

Root Causes- Management Factors

Inadequate Monitoring / Supervision

Direct Causes- Unsafe Conditions

Defective Equipment, Machinery or Tools

Direct Causes- Unsafe Acts

Failure to Follow Repair / Maintenance Instructions

Follow Up

On	By	Follow Up	
13/May/2024	Nawin Khaware	Pls upload all the reports and photographs here after crane repairs.	
12/May/2024	Cristian Ion Petrache Staff Code - 10566 - MST	Crane in underprocess of maintenance. Waiting shore team next Point Lisas on 18.05.2024 to complete jobs.	

Before & After Pictures

Before	After