

## **B. 5.20 - DRILL REPORT**

Date : 10/08/2018 Page : 1 of 2

Made by : QHSE Approved by : MD Rev. No : 0

Vessel :MT BITU ATLANTIC Date (dd/mm/yy):28.10.2018 Location:AT SEA

Type of Drill : EMERGENCY STEERING

**Description of Planned Drill: -**

ACTION TO BE TAKEN IN CASE OF STEERING FAILUIRE / EMERGENCY STEERING

### **SOLAS** Requirements for Conducting Abandon Ship Drill and Fire Drill:

## SOLAS Ch III Reg 19 3.3 Requires Abandon Ship Drill Should Include atleast following: -

- Raising of Alarm and Mustering of Crew at Muster stations,
- Preparing for Their Duties as described in Muster List,
- Checking that Crew is appropriately dressed and Life jackets properly donned,
- Lowering of at least one Life boat after necessary preparation, (Not for free fall Life Boats),
- Starting and operating Life boat Engine,
- Operating Davits used for Launching Life rafts,
- Mock search and Rescue of Crew Trapped in Staterooms,
- Instructions in use of Radio Life Saving Appliances.

## SOLAS Ch III Reg 19 3.4 Requires Fire Drill Should Include at least following: -

- Fire Drills should be planned so as to have regular practice in various emergencies that may occur depending upon type of vessel,
- Reporting for stations and Preparing for Their Duties as described in Muster List,
- Starting Fire pump using at least 2 jets of water,
- Checking of fireman's outfit and other personal rescue equipments,
- Checking operation of water tight doors, fire doors, fire dampers and ventilation systems in area of drill,
- Check necessary arrangements for subsequent abandoning of the ship.

# Log Of Events Of Drill: - Each and every reported event to Bridge has to be recorded with time as below: -

# After initial Alarm Sounded crew muster at Emergency Muster Station: -

Time	Event	Reported By
1700	Alarm Sounded, Nature of drill declared by Master EMERGENCY STEERING	MASTER
1701	Crew Mustered	CH OFF
1702	Head Count Taken- Missing Persons None	CH.OFF
1704	Checking of PPE Done	CH.OFF
1705	Duties Checked / Explained	CH.OFF

#### Master declares the nature of emergency and Emergency team Organisation done as below: -

Time	Event	Reported By
1707	Immediate action to be taken, emergency change over procedures and NFU explained.	CH.OFF
	Gmdss station manned broad cast Pan Pan , NUC displayed, chart assesment for proximity of navigational harzards.	2ND OFF
	Communication from steering gear flat to bridge by emergency telephone checked ,emergency steering tried out by all crew	2ND ENG
	Fault to retified and repair carried out ,office and required parties notified.	2ND ENG



## B. 5.20 - DRILL REPORT

Date	: 10/08/2018
Date Page	: 2 of 2

Made by : QHSE Approved by : MD Rev. No : 0

	Debriefed , Crew respose satisfactory.	CH OFF
1745	Drill called-off by master.	MASTER

Evaluation of Drill for improving the training and response of crew in emergency: - This Should be based upon follwoing: -

- Response of Crew in Drill as observed by all Team Leaders and Master,
- Feedback from Crew Members for effective improvemnet of Response,
- Identification for Further training requirements should be aimed for improvement.

A	LL	SA	TIS	SF/	\C1	O	R١	۲.

## **Drill Attendance Log:-**

Sr. No	Name	Rank
1	CAPT. PANAIT MARIN	MASTER
2	GURDAS SINGH	CH.OFF
3	SILVESTRE A FERNANDES	3RD OFF
4	ANDRIESANU DUMITRU	CH.ENG
5	ANGELADA ARSENIO JR. CERVANTES	2ND ENG
6	MARTINEZ LEOLOR ADAM BEQUILLA	4TH ENG
7	KARTHIKEYAN KRISHNAN MOOKIA	ELEC.OFF
8	ADI VENANCIO MONDEJAR	BOSUN
9	BAILO LYNDON BANDOLA	PUMPMAN
10	LUMAWAG JEFFREY RIEGO	AB-1
11	OLAC WILMAR TIPSAY	AB-2
12	DE MESA JOE VENSON	AB-3
13	AMPOLOQUIO LEO RABI	OS-1
14	PAJO JIMBOY VILLANUEVA	OS-2
15	SILIGAN GREGORIO JR	FTR-1
16	MATTUPURATH GEORGE	FTR-2
17	LABRADOR RYAN AROLLADO	OILER-1
18	SEBUCO MARK ANTHONY EMBOLODE	OILER-2
19	ABELA ROLLY DACILLO	WIPER
20	SIBAYAN DENNIS	CH.COOK
21	BAUTO JERWIN CHUAHAP	MESSMAN
22	SHARMA GAGANDEEP	ELEC.SUPT

Safety Officer : - Name: Gurdas singh

Master : - Name: Captain Panait Marin