

# **Maritec Tanker Management**

# **Before & After pics**

Vessel: Bitu Express

Defect ID: 125

NCR # : 11/2021

## **Applicable Dates**

Date Raised: 22/Sep/2021

ETC: 29/Sep/2021

#### **Defect Details**

Oil spill on deck portside front of accommodation due to bunker line pipe leakage.

#### **Before & After Pictures**

# Before\_Picture After\_Picture FILE NOT FOUND

Before and After pics Printed On: 12/Oct/2021 1/12





Vessel: Bitu Express

Defect ID: 123

NCR # : 9/2021

# **Applicable Dates**

Date Raised: 13/Sep/2021


ETC: 18/Sep/2021

Before and After pics Printed On: 12/Oct/2021 2/12

## **Defect Details**

Deck Bunker line on portside, front of accommodation, has leakage from a hole on pipe.

#### **Before & After Pictures**





Before and After pics Printed On: 12/Oct/2021 3/12



Vessel: Bitu Atlantic

Defect ID: 150

# Applicable Dates

Date Raised: 31/Jul/2021

ETC: 08/Sep/2021

#### **Defect Details**

Soot collection tank is in poor condition- maintenance required

## **Before & After Pictures**

Before\_Picture After\_Picture

Before and After pics Printed On: 12/Oct/2021 4/12









Vessel: Bitu Atlantic

Defect ID: 143

# Applicable Dates

Date Raised: 31/Jul/2021

ETC: 20/Sep/2021

# **Defect Details**

Before and After pics Printed On: 12/Oct/2021 5/12

Steam dump condenser- frequent chocking of tubes.

**Before & After Pictures** 

## Before\_Picture



# After\_Picture







Before and After pics Printed On: 12/Oct/2021 6/12










Before and After pics Printed On: 12/Oct/2021 7/12









Vessel: Bitu Atlantic

Defect ID: 141

# Applicable Dates

Date Raised: 31/Jul/2021

ETC: 20/Sep/2021

# **Defect Details**

Before and After pics Printed On: 12/Oct/2021 8/12

## Few SW valves are not holding

# **Before & After Pictures**

## Before\_Picture



# After\_Picture







Before and After pics Printed On: 12/Oct/2021 9/12









Before and After pics Printed On: 12/Oct/2021 10/12









Vessel: Bahama Blue

Defect ID: 59

# Applicable Dates

Date Raised: 17/Jun/2021


ETC: 01/Jul/2021

## **Defect Details**

Before and After pics Printed On: 12/Oct/2021 11/12

VDR Abnormal

Please note that VDR screen is not normal, we restarted no response. It looks it is not booting. We refer the manual no explanation about it. Needs maker/Remote advice Showing: CCP BIOS A18009-R1a(VDR)



Before and After pics Printed On: 12/Oct/2021 12/12