



Maritec Tanker Management Private Limited

Incident Reports Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Biskra	Defect ID : 157	NCR # : 14/2023	Is NCR ? : Yes
-----------------	-----------------	-----------------	----------------

Defect Details

M.T.BISKRA alongside at Standard Flour Mills Berth, ON 02.12.2023 @ 1212 HLT one Stowaway was found in the CO2 ROOM hiding behind the Foam Tank. The alarm was raised immediately. Investigation made and complete stowaway search performed in all areas of the ship.

Requisition Code :

Categories

Primary :	Incident	Inspector - Internal :		Vessel Dept :	Deck
Secondary :	Lack of Situational Awareness	Inspector External :		Office Dept :	Operations
		Inspection Date :			

Applicable Dates

Date Raised : 02-Dec-2023	ETC : 09-Dec-2023	Date Completed :
---------------------------	-------------------	------------------

Other Details

Priority : Normal	Assigned By : Vessel	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

Causes

-failure to maintain proper security watch at gangway

Corrective Action

-Crew and security guards briefed about the security measured to be maintained continuously at port.

Preventive Action

-Proper security watch to be maintained all the time while vessel at port

CONTRIBUTING FACTORS

Root Causes- Personal Factor

Situational Awareness

Direct Causes- Unsafe Acts

Failure to Follow Rules and Regulations

Follow Up

On	By	Follow Up	
----	----	-----------	--

Before & After Pictures

Before

After