



## Maritec Tanker Management

### Incident Report's Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

Vessel : Bitu Atlantic	Defect ID : 173	NCR # :	Is NCR ? : No
------------------------	-----------------	---------	---------------

#### Defect Details

Bosun while using Bathroom, Bumped his right greater tow on door bottom frame & resulted minor injury on his greater tow nail.

Requisition Code :

#### Categories

Primary :	Incident	Inspector - Internal :		Vessel Dept :	Deck
Secondary :	Other	Inspector External :		Office Dept :	Safety
		Inspection Date :			

#### Applicable Dates

Date Raised : 12-Nov-2021	ETC : 30-Nov-2021	Date Completed : 10-Dec-2021
---------------------------	-------------------	------------------------------

#### Other Details

Priority : Normal	Assigned By : Vessel	Verified By : Nawin Khaware
Display in Daily Meeting? : No	SFI :	Verified On : 22/Dec/2021

#### Causes

#### Corrective Action

#### Preventive Action

#### Applicable Tags

#### Root Causes- Management Factors

Inadequate Design

#### Follow Up

On	By	Follow Up	
22/Dec/2021	Nawin Khaware	This incident is same as of #172. so just refer #172 for all applicable actions.	
24/Nov/2021	Nawin Khaware	Please provide further updates on his treatment.	
12/Nov/2021	ASHOK DHAMAL   Staff Code - 10261 - C/OFF	Contacted Company authorised doctor for further treatment, discussed incident among crew members	

#### Before & After Pictures

Before



After

