



Maritec Tanker Management

Incident Report's Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Biskra	Defect ID : 57	NCR # :	Is NCR ? : No
-----------------	----------------	---------	---------------

Defect Details

Crew Member was welding a pipe in Engine Room workshop, After he had welded some portion he opened up Face Shield and tried to remove welding flux with small chipping tool, resulted small partical of metal fallen in the Left eye, Later given first Aid onboard (immediately Eye cleaned with Eye wash), Available Eye drop given, Request raised for Shore Medical help.

Requisition Code :

Categories

Primary :	Incident	Inspector - Internal :		Vessel Dept :	Engine
Secondary :	Other	Inspector External :		Office Dept :	Safety
		Inspection Date :			

Applicable Dates

Date Raised : 13-Aug-2021	ETC : 13-Aug-2021	Date Completed : 13-Aug-2021
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Vessel	Verified By : Nawin Khaware
Display in Daily Meeting? : No	SFI :	Verified On : 28/Oct/2021

Causes

Unsafe act by fitter as using chipping hammer without any eye protection.

Corrective Action

Eye wash used to clean his eyes. First aid was administered.

Preventive Action

Use proper PPE for the type of job engaged with.

Applicable Tags

Job Factors

Other Job Factors

Follow Up

On	By	Follow Up	
28/Oct/2021	Nawin Khaware	We consider this incident as closed now.	
21/Aug/2021	Asfaha Tekeste Gebremichael Staff Code - 10368 - MST	EXPECTED COMPLETION DATE for this job has been changed from 17/Aug/2021 to 13/Aug/2021	

13/Aug/2021	GAJANAN PRIOLKAR Staff Code - 10176 - 2/E	Immediately Safety Meeting to be carried out, Crew needs to use proper PPE while working.	
-------------	--	---	--

Before & After Pictures

Before	After
--------	-------

