

Maritec Tanker Management Incident Report's Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel: Biskra Defect ID: 59 NCR #: 5/2021 Is NCR ?: Yes

Defect Details

4/E Anish Verma had his left hand palm open fracture of finger No-M4 & M5 while shifting the empty oil drums from poop deck to A-deck

Requisition Code:

Categories								
Primary :	Incident	Inspector - Internal:	Nawin Khaware	Vessel Dept:	Engine			
Secondary :	Lack of Situational Awareness	Inspector External :		Office Dept:	Safety			
		Inspection Date :						

Applicable Dates

Other Details	Other Details					
Priority : Normal	Assigned By: Vessel	Verified By: Nawin Khaware				
Display in Daily Meeting? : No	SFI:	Verified On: 21/Dec/2021				

Causes

4/E Anish Verma had his left hand palm open fracture of finger no-M4 & M5 while shifting the empty oil drums from poop deck to A-deck

Corrective Action

Proper procedures to be followed while carrying out any work on board,safe working practices to followed at all times,tool box meeting to be carried out before doing any job.

Preventive Action

HOD to monitor the job analysis before carrying out any job on board, competent person should be assigned to carry out the respective job.

Applicable Tags

Descriptions

Injury

Root Causes- Job Factor

Inadequate Work Standards

Root Causes- Management Factors

Inadequate Monitoring / Supervision

Incident Report's Details Printed On: 25-Jan-2022 1/7

Root	Сапеде-	Personal	Factor

Lack of Knowledge

Direct Causes- Unsafe Acts

Improper Lifting, Handling or Storage

Job Factors

Inadequate Supervision

Personal Factors

Lack of Knowledge

Follow Up

On	Ву	Follow Up	
21/Dec/2021	Nawin Khaware	This report can be considered as closed now.	
14/Dec/2021	Azheruddin SAWANT Staff Code - 10175 - 3/OFF	4TH ENG ANISH REPORTS	Link1 Link2 Link3 Link4 Link5
14/Dec/2021	Nawin Khaware	Root cause analysis: 1. Unsupervised work 2. Inadequate Risk perceived. 3. Improper handling	

Before & After Pictures

Before After

Incident Report's Details Printed On: 25-Jan-2022 2/7



































