



Maritec Tanker Management

Incident Report's Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bahama Blue	Defect ID : 57	NCR # : 2/2021	Is NCR ? : Yes
----------------------	----------------	----------------	----------------

Defect Details

Port thruster high temperature safety activated and stopped the thruster. ship was transiting from trinidad to guyana. abnormal noise and vibration were observed in gearbox

Requisition Code :

Categories

Primary :	Incident	Inspector - Internal :	Francis Timothy Monteiro	Vessel Dept :	Engine
Secondary :	Other	Inspector External :		Office Dept :	Technical
		Inspection Date :	01-Aug-2021		

Applicable Dates

Date Raised : 18-Jun-2021	ETC : 21-Jul-2021	Date Completed : 01-Aug-2021
---------------------------	-------------------	------------------------------

Other Details

Priority : Urgent Defect deferred to DD	Assigned By : Vessel	Verified By : Nawin Khaware
Display in Daily Meeting? : No	SFI :	Verified On : 28/Oct/2021

Causes

Material Failure

Corrective Action

Replaced new lower gearbox and changed oil with environmental friendly oil

Preventive Action

Maintain constant checks during rounds.

Applicable Tags

Follow Up

On	By	Follow Up	
28/Oct/2021	Nawin Khaware	Vessel called for DD at Santo Domingo for carrying out permanent repair of Port thruster. System is up for running and back to normal now. We can consider this report as closed now.	

Before & After Pictures

Before	After
--------	-------

