



Maritec Tanker Management Private Limited

Incident Reports Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Asphalt Teranga	Defect ID : 196	NCR # : 38/2023	Is NCR ? : Yes
--------------------------	-----------------	-----------------	----------------

Defect Details

During PSC inspection on 29.09.2023

Two wipers of the bridge navigation windows were found out of order

Requisition Code :

Categories

Primary :	Incident	Inspector - Internal :		Vessel Dept :	Deck
Secondary :	Procedures not Followed	Inspector External :		Office Dept :	Safety
		Inspection Date :			

Applicable Dates

Date Raised : 29-Sep-2023	ETC : 30-Sep-2023	Date Completed : 30-Sep-2023
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Vessel	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

Causes

Lack of maintenance

Corrective Action

Wipers removed, cleaned, greased and installed. Tested and found operational.

Preventive Action

Regular maintenance to be carried out as per PMS

Applicable Tags

Follow Up


On	By	Follow Up	
09/Oct/2023	Alexander DUBAKOV Staff Code - 10564 - C/OFF	AWAITING OFFICE ACTION for this job has been changed to Yes	

Before & After Pictures

Before	After
--------	-------




Notification

 File Not Uploaded



Notification

 File Not Uploaded