

Maritec Tanker Management Private Limited

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Incident Reports Details

Defect Details

During PSC inspection on 29.09.2023

Information required by the deck logbook format is not properly recorded. The trip cannot be clearly restored following the logbook entries. Master instructed to keep proper records from now on.

Requisition Code:

Categories	ategories					
Primary :	Incident	Inspector - Internal:		Vessel Dept:	Deck	
Secondary :	Lack of Training	Inspector External :		Office Dept:	Safety	
		Inspection Date :				

Applicable Dates

Other Details					
Priority : Normal	Assigned By: Vessel	Verified By: Nawin Khaware			
Display in Daily Meeting? : No	SFI:	Verified On: 13/Oct/2023			

Causes

Incorrect Logbook entries

Corrective Action

Master instructed OOW that entries and records to be written clearly in Deck Logbook.

Preventive Action

Master carried out training for deck officer on how to write log entries correctly and that company policies and procedures must be adhered to always.

CONTRIBUTING FACTORS

Root Causes- Management Factors

Document / Drawing Control Issue

Inadequate Monitoring / Supervision

	Fol	low	U	b
--	-----	-----	---	---

On	Rv	Follow Up	
OII	- y	Tollow op	

Incident Reports Details Printed On: 20-Mar-2024 1/2

Before After

ONBOARD TRAINING RECORD

SHIP NAME: ASPHALT TERANGA

TYPE OF TRAINING: LOG BOOK ENTRIES & POSITION FIXING (LOP)

DATE: 02.10.2023 LOCATION: AT SEA

TRAINING REPORT:

Master carried out training for deck officer on how to write log entries correctly and position fixing (LOP) on ECDIS. Company policies and procedures must be adhered to always and passage plan instructions to be followed as per position fixing means and methods.

Well understood.





Notification



File Not Uploaded