

Before

Maritec Tanker Management Private Limited


Ship File No : N/A Office File No: N/A Form No : N/A Issue N/A Revision : N/A

Incident Reports Details

Rev Date Vessel: Asphalt Teranga Defect ID: 195 NCR # : 37/2023 Is NCR?: Yes **Defect Details** During PSC inspection on 29.09.2023 The ship's crew couldn't provide evidence for the operation of the UMS system for several days in August. Requisition Code: Categories Primary: Incident Inspector - Internal: Vessel Dept: Deck Miscommunic Inspector External: Office Dept: Safety Secondary: ation Inspection Date : **Applicable Dates** Date Raised: 29-Sep-2023 ETC: 30-Sep-2023 Date Completed: 30-Sep-2023 Other Details Priority: Normal Assigned By: Vessel Verified By: Nawin Khaware Display in Daily Meeting? : No SFI: Verified On: 13/Oct/2023 Causes PSC inspector in doubt **Corrective Action** Evidence of UMS system showed in Engine Log Book **Preventive Action** Log entries to be checked and verified by HOD. **CONTRIBUTING FACTORS** Follow Up On Ву **Follow Up Before & After Pictures**

After









File Not Uploaded

Notification










File Not Uploaded

Notification











File Not Uploaded

Notification











File Not Uploaded

Notification









File Not Uploaded

Notification

