



Maritec Tanker Management Private Limited

Incident Reports Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Asphalt Teranga	Defect ID : 189	NCR # : 31/2023	Is NCR ? : Yes
--------------------------	-----------------	-----------------	----------------

Defect Details

During PSC inspection on 29.09.2023
CSR doc. No.5 and 6 are available in copy only

Requisition Code :

Categories

Primary :	Incident	Inspector - Internal :		Vessel Dept :	Deck
Secondary :	Other	Inspector External :		Office Dept :	Management
		Inspection Date :			

Applicable Dates

Date Raised : 29-Sep-2023	ETC : 30-Sep-2023	Date Completed : 30-Sep-2023
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Vessel	Verified By : Nawin Khaware
Display in Daily Meeting? : No	SFI :	Verified On : 13/Oct/2023

Causes

Documentation issue - CRS document No.5 and 6 not available in original copy

Corrective Action

We assumed the responsibility of this vessel in April 2022 and the identified CSR is from previous operator which are for year 2019 & 2020. Tried reaching out to the previous operator at the time of hand over however they have advised that their class were issuing soft copy CSR only.

Preventive Action

CSR copy must be maintained in original copy onboard. Some of the Flags do provide only soft copy CSR like MI. Flag.

CONTRIBUTING FACTORS

Root Causes- Management Factors

Document / Drawing Control Issue

Follow Up

On	By	Follow Up	
13/Oct/2023	Nawin Khaware	Issues has been discussed with previous operator and basis their clarification that previous Flag was only issuing soft copy CSR. So based on this fact, consider this point as closed out now.	

Before & After Pictures

Before

After