

Vessel	Job ID	Assignor	Date Raised Date Completed	Job Description	Job Progress
OFFC	1 1/2021	Crew Complaint	13/Oct/2021 Pending	Defect List & NCRs test 13oct2021	13/Oct/2021 (Jot Support6) : Followup Details1 13/Oct/2021 (Jot Support6) : Followup Details 13/Oct/2021 (Jot Support6) : Followup 1
BITX	125 11/2021	Vessel	22/Sep/2021 Pending	Oil spill on deck portside front of accommodation due to bunker line pipe leakage.	22/Sep/2021 (Gelu Antin Staff Code - 10124 - MST) : Bunker pipe was temporary repaired by ship staff. Bunker line was tested after temporary repairs by ship staff.
BITX	123 9/2021	Vessel	13/Sep/2021 Pending	Deck Bunker line on portside, front of accommodation, has leakage from a hole on pipe.	15/Sep/2021 (Gelu Antin Staff Code - 10124 - MST) : Currently temporarily repaired.
BISK	40 1/2021	HSQE Suptd	18/Feb/2021 Pending	NC 01/2021 - Accurate jobs are not assigned in JOT PMS for the rank of 3OF, while checking it was found that some other irrelevant jobs are assigned under the responsibility of 3OF, same needs to be corrected on priority as PMS plays an integral role in carrying out routine maintenance of the ship's machineries/equipments which ensures safe operation of the ship which leads to protection of environment	03/Jun/2021 (Francis Timothy Monteiro) : ETC has been changed from "15 May 2021" to "15 Jun 2021".
BBLU	51 1/2021	Vessel	13/Feb/2021 Pending		19/Mar/2021 (Nawin Khaware) : This was a test report o verify if system is functioning properly. 03/Mar/2021 (Rakesh Kumar) : The Near Miss is not reflected for which the Cause/Corrective Action and Preventive Action has been displayed.