



Maritec Tanker Management

Non Conformance Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Atlantic	Defect ID : 294	NCR # : 8/2023	Is NCR ? : Yes
------------------------	-----------------	----------------	----------------

Defect Details

Few Fire doors inside accommodation 'A' deck were found not closing automatically.

Requisition Code :

Categories

Primary :	LSA/FFA	Inspector - Internal :	Fiacre Fonseca	Vessel Dept :	Deck
Secondary :	Fire Fighting Appliances	Inspector External :		Office Dept :	Operations
		Inspection Date :	08-Aug-2023		

Applicable Dates

Date Raised : 08-Aug-2023	ETC : 15-Aug-2023	Date Completed : 19-Aug-2023
---------------------------	-------------------	------------------------------

Other Details

Priority : Urgent	Assigned By : HSQE Suptd	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

Causes

Corrective Action

Preventive Action

Applicable Tags

Root Causes- Job Factor

Inadequate Maintenance

Follow Up

On	By	Follow Up	
20/Aug/2023	Cosmin Otelea Staff Code - 10502 - C/OFF	The closing system for Fire doors inside accommodation 'A' deck was adjusted for proper working condition.	
09/Aug/2023	Fiacre Fonseca		

Before & After Pictures

Before

After

