



Maritec Tanker Management

Non Conformance Details

Ship File No : N/A
 Office File No : N/A
 Form No : N/A
 Issue : N/A
 Revision : N/A
 Rev Date : N/A

Vessel : Bahama Blue	Defect ID : 180	NCR # : 3/2023	Is NCR ? : Yes
----------------------	-----------------	----------------	----------------

Defect Details

During annual inspection by US Coastguard made deficiency Code 11122(SOLAS 20 III/6.2.2):
 On ships carrying at least two Search&Rescue locating devices and equipped with free fall life boats one of the search and rescue locating devices shall be stowed in the fre fall life boat. There was no search and rescue locating device stored in the free fall life boat.

Requisition Code :

Categories

Primary :	LSA/FFA	Inspector - Internal :		Vessel Dept :	Deck
Secondary :	Life Saving Appliances	Inspector External :		Office Dept :	Operations
		Inspection Date :			

Applicable Dates

Date Raised : 09-Feb-2023	ETC : 16-Feb-2023	Date Completed : 09-Feb-2023
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Vessel	Verified By : Nawin Khaware
Display in Daily Meeting? : No	SFI :	Verified On : 28/Feb/2023

Causes

Company procedure prescribed as per Muster list for 2nd Officer duties to bring SART into the fre fall life boat during emergency/drills.

Corrective Action

SART transferred and stowed into free fall life boat as per SOLAS regulation.

Preventive Action

Keep reference to last amendments for SOLAS.

Applicable Tags

Follow Up

On	By	Follow Up	
09/Feb/2023	Valentin MITENKOV Staff Code - 10552 - MST	SART located on the bridge assigned for 2nd Officer duties by muster list to bring this into life boat. SART was stowed in the fre fall life boat to satisfy requirements of US Coastguard.	Link1 Link2 Link3

Before & After Pictures

Before



After

