

Maritec Tanker Management Private Limited

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

Non Conformance Details

Vessel : Bisk	ra [Defect ID	0 : 193	NCR # : 5/2024	4	Is NCR ? : Yes			
Defect Details									
15 PPM Oil monitoring system modified to bypass sampling									
Requisition Code :									
Categories									
Primary :	E/R Machinery	Inspe	ctor - Internal :		Vessel Dept	: Engine			
Secondary :	Miscellaneous	Inspe	ctor External :		Office Dept	: Technical			
		Inspe	ction Date :	18-Apr-2023					
Applicable Dates									
Date Raised : 17-Apr-2023			ETC : 20-Apr-2023		Date Comp	Date Completed : 20-Apr-2023			
Other Details									
Priority : Urgent			Assigned By : Port State Control		Verified By	Verified By : Nawin Khaware			
Display in Daily Meeting? : No			SFI :		Verified On	Verified On : 05/Jul/2024			
Causes									
Failure to comply with company procedure and MARPOL regulations, as per M78/Annex1/15.									
Corrective Action									
All byepass arrangement will be remove and to be returned as per manufacturers procedures and instruction.									
Preventive Action									
Regular training of crew and complianec to safe practices with proper supervision. will ensure full complianec to all relevant regulations.									
CONTRIBUTING FACTORS									
Descriptions									
Environmental Pollution									
Root Causes- Job Factor									
Inadequate Engineering									
Root Causes- Management Factors									
Inadequate Monitoring / Supervision									
Direct Causes- Unsafe Conditions									

Hazardous Environmental Condition

Direct Causes- Unsafe Acts

Incorrect Use of Equipment or Machinery

Job Factors

Inadequate Maintenance or Not Done as per Manufacturer's Schedules

Personal Factors

Inadequate Experience

Substandard Acts

Failure to follow procedure


Substandard Conditions

Hazardous Environmental Condition

Follow Up							
On	Ву	Follow Up					
05/Jun/2024	Nawin Khaware	Upload evidence of closures					
03/Jun/2024	Loreto Caracena br/> Staff Code - 10154 - MST	Priority for this job has been changed from to URGENT					

Before & After Pictures

Before



After

