

Maritec Tanker Management Private Limited

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Non Conformance Details

 Vessel : Biskra
 Defect ID : 195
 NCR # : 7/2024
 Is NCR ? : Yes

Defect Details

Cargo tank 2C PV valve defective.

Requisition Code:

Categories								
Primary :	Cargo Handling	Inspector - Internal:		Vessel Dept :	Deck			
Secondary:	Cargo Measuring/ Test Equipment	Inspector External :		Office Dept:	Technical			
		Inspection Date :	18-Apr-2023					

Applicable Dates

Other Details

Priority : Urgent Assigned By : Port State Control Verified By : Nawin Khaware

Display in Daily Meeting? : No SFI: Verified On : 05/Jul/2024

Causes

Inadequate maintenance and no frequent checks as per company procedures.

Corrective Action

Overhauld of the system will be carried out.

Preventive Action

Regular checks and maintenance will be carried out as per company procedures.

CONTRIBUTING FACTORS

Descriptions

Damage to Vessel

Root Causes- Job Factor

Inadequate Maintenance

Job Factors

Inadequate Maintenance or Not Done as per Manufacturer's Schedules

Non Conformance Details Printed On: 05-Jul-2024 1/2

Follow Up								
On	Ву	Follow Up						
Before & After Pictures								
Before			After					

Non Conformance Details Printed On: 05-Jul-2024 2/2