

Maritec Tanker Management Private Limited

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

Rev Date

Non Conformance Details

Vessel: Biskra Defect ID: 194 NCR #: 6/2024 Is NCR ?: Yes

Defect Details

15 PPM alarm arrangement defective.

Requisition Code:

Categories								
Primary :	E/R Machinery	Inspector - Internal:		Vessel Dept:	Engine			
Secondary :	Miscellaneous	Inspector External :		Office Dept:	Technical			
		Inspection Date :	20-Apr-2023					

Applicable Dates

Other Details

Priority: Urgent

Assigned By: Port State Control

Verified By: Nawin Khaware

Display in Daily Meeting?: No

SFI:

Verified On: 05/Jul/2024

Causes

Inadequate maintenance with no proper routine checks in place.

Corrective Action

Trouble shooting and repair/replacement of defective part will be carried out. If required, requisition will be raised for same.

Preventive Action

Proper routine maintenance and routine test should be mauntained at all time as per company procedures.

CONTRIBUTING FACTORS

Descriptions

Pollution

Root Causes- Job Factor

Inadequate Maintenance

Direct Causes- Unsafe Acts

Failure to Follow Repair / Maintenance Instructions

Follow Up

Non Conformance Details Printed On: 05-Jul-2024 1/2

On	Ву	Follow Up						
Before & After Pictures								
Before			After					

Non Conformance Details Printed On: 05-Jul-2024 2/2