

Maritec Tanker Management

Non Conformance Details

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

Rev Date

Vessel: Morbihan Defect ID: 75 NCR #: 1/2023 Is NCR ?: Yes

Defect Details

Vessel facing problem during taking cargo tank ullage as both UTI landed shore for servicing and vessel does not have any standby UTI.

Vessel have 2 MMC which is open type (During Ullaging time-vapour comes out) and only have interface reading.

Requisition Code:

Categories					
Primary :	Cargo Handling	Inspector - Internal:		Vessel Dept:	Deck
Secondary :	Cargo Measuring/ Test Equipment	Inspector External :		Office Dept:	Operations
		Inspection Date :	17-Jan-2023		

Applicable Dates

Date Raised: 18-Jan-2023 ETC: 25-Jan-2023 Date Completed: 13-Apr-2023

04	0.00	Dat	ails
4011			

Priority: Urgent Assigned By: Vessel Verified By:

Display in Daily Meeting?: No SFI: Verified On:

Causes

job factors

Corrective Action

Preventive Action

Applicable Tags

Root Causes- Job Factor

Excessive Wear and Tear

Direct Causes- Unsafe Conditions

Defective Equipment, Machinery or Tools

Follow Up

On	By	Follow Up	
OII	Бу	Follow op	

Non Conformance Details Printed On: 27-Jul-2023 1/2

20/May/2023	Oleg Kisiliuk Staff Code - 10558 - C/OFF	On board two UTI with calibration certificate and in good condition	Link1 Link2
03/Mar/2023	Giorgica Mardaru br/> Staff Code - 10548 - MST	On February 24, I received an UTI at DDC	Link1
18/Jan/2023	Cosmin Otelea - Staff Code - 10502 - C/OFF	Waiting for UTI on board after servicing.	

Before	& Aft	er P	ictures
---------------	-------	------	---------

Before	After