



Maritec Tanker Management

Non Conformance Details

Ship File No : N/A
 Office File No : N/A
 Form No : N/A
 Issue : N/A
 Revision : N/A
 Rev Date : N/A

Vessel : Bitu Atlantic	Defect ID : 72	NCR # : 3/2020	Is NCR ? : Yes
------------------------	----------------	----------------	----------------

Defect Details

07124 Fire hose of Fire Hydrant at forcastle found leaking from a small hole during Emergency Fire Pump pressure test

Requisition Code :

Categories

Primary :	Near Miss	Inspector - Internal :		Vessel Dept :	Deck
Secondary :	Inadequate Maintenance / Wear and Tear	Inspector External :		Office Dept :	Safety
		Inspection Date :			

Applicable Dates

Date Raised : 20-Mar-2020	ETC : 28-Mar-2020	Date Completed : 20-Mar-2020
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Vessel	Verified By : Rakesh Kumar
Display in Daily Meeting? : No	SFI :	Verified On : 21/Mar/2020

Causes

A condemned hose was used instead of new supplied one

Corrective Action

Hose replaced on the spot

Preventive Action

Crew to be aware of condemned equipment not to be used, equipment to be properly marked with "NOT IN USE" poster/markings

Applicable Tags

Follow Up

On	By	Follow Up	
21/Mar/2020	Rakesh Kumar	Port State Control in its report has marked this as rectified.	
21/Mar/2020	Rakesh Kumar	Port State Control in its report has marked this as rectified.	
21/Mar/2020	Rakesh Kumar	Port State Control in its report has marked this as rectified.	

21/Mar/2020	Rakesh Kumar	Port State Control in its report has marked this as rectified.	
21/Mar/2020	Rakesh Kumar	Port State Control in its report has marked this as rectified.	
21/Mar/2020	Rakesh Kumar	Port State Control in its report has marked this as rectified.	
21/Mar/2020	Rakesh Kumar	Port State Control in its report has marked this as rectified.	
21/Mar/2020	Rakesh Kumar	Port State Control in its report has marked this as rectified.	
21/Mar/2020	Rakesh Kumar	Port State has confirmed the observations as rectified in the report issue.	
21/Mar/2020	Rakesh Kumar	Port State has confirmed the observations as rectified in the report issue.	
21/Mar/2020	Rakesh Kumar	Port State has confirmed the observations as rectified in the report issue.	
21/Mar/2020	Rakesh Kumar	Port State has confirmed the observations as rectified in the report issue.	
21/Mar/2020	Rakesh Kumar	Port State has confirmed the observations as rectified in the report issue.	
21/Mar/2020	Rakesh Kumar	Port State has confirmed the observations as rectified in the report issue.	
21/Mar/2020	Rakesh Kumar	Port State has confirmed the observations as rectified in the report issue.	
21/Mar/2020	Gelu Antin	Hose removed and replaced with new one	

Before & After Pictures	
Before	After