



## Maritec Tanker Management

### Non Conformance Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

Vessel : Bitu Atlantic	Defect ID : 71	NCR # : 2/2020	Is NCR ? : Yes
------------------------	----------------	----------------	----------------

#### Defect Details

07199 Pieces of insulation was missing to Emergency Diesel Generator exhaust gas elbow pipe (approx. 40 cm) and to Thermal Boiler Room Aft PS two pieces of insulation missing from steam pipes

Requisition Code :

#### Categories

Primary :	Near Miss	Inspector - Internal :		Vessel Dept :	Engine
Secondary :	Poor Housekeeping	Inspector External :		Office Dept :	Technical
		Inspection Date :			

#### Applicable Dates

Date Raised : 20-Mar-2020	ETC : 28-Mar-2020	Date Completed : 21-Mar-2020
---------------------------	-------------------	------------------------------

#### Other Details

Priority : Normal	Assigned By : Port State Control	Verified By : Rakesh Kumar
Display in Daily Meeting? : No	SFI :	Verified On : 21/Mar/2020

#### Causes

Wear and tear of insulation material

#### Corrective Action

All pipes insulated

#### Preventive Action

More careful inspections to be carried by Ship's responsible staff to avoid damage to equipment

#### Applicable Tags

#### Follow Up

On	By	Follow Up	
21/Mar/2020	Gelu Antin	Pipes were insulated as requested.	

#### Before & After Pictures

Before	After
--------	-------

