

## **Near Miss Details**

Guidance: 01) Please do not mention any names in the near miss report. 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.										
03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED Vessel : Asphalt Teranga				D IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT. Defect ID : 147						
Defect Details										
while taking rounds I observed resuce boat engine fuel hose was broken leaking the fuel. Same renewed the hose and tested found working satisfactory.										
Requisition Code :										
Categories										
Primary :	Near Mis	Near Miss		Dept :	Deck					
Secondary :	Other	Other		Dept :	Technical					
Applicable Dates										
Date Raised : 01-Jun-2023				Date Completed : 19-Ju	leted : 19-Jun-2023					
Other Details										
Priority :	Normal	QMS Elements Ref :		- SELECT -	Verified By :	Nawin Khaware				
Show in Monthly Safety Meeting? :	No	SFI :			Verified On :	19/Jun/2023				
Potential to become a serious accident : Low Recurrence : Low										
Causes										
Slippery surface due leak from L/B engine fuel hoses. Also rendering the L/B engine inoperable due oil leak.										
Corrective Action										
COF was alerted and the deck area was cleaned immediately, ensured no iil has gone overboard. Damage hose was repaired and tested L/B engine & found working satisfactory.										
Preventive Action										
Follow PMS routines for L/B sincerely with special attention to be paid on all the items susceptible for wear & tear. Spare hoses for L/B engine fuel oil system must be maintained onboard at all times.										
Applicable Tags										
Root Causes- Job Factor										
Excessive Wear and Tear										
Inadequate Maintenance										
Follow Up										

On	Ву	Follow Up						
19/Jun/2023	Nawin Khaware	ETC has been ch 2023".	anged from "08 Jun 2023" to "20 Jun					
19/Jun/2023	Nawin Khaware	With suggested p could be conside	preventive measures, this NM report red as closed now.					
Before & After Pictures								
Before			After					