



Maritec Tanker Management Private Limited

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Kensington LG

Defect ID : 36

Defect Details

During cleaning of Engine Room Aft Bilge well, a crew went down to the tank top level for taking the remaining bilge water from the bilge well. Unfortunately, he was slip from the pipe he steps on due to slippery area. Still he got his balance since his hand hold from the ER flooring and no pain was observed and reported.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Poor Housekeeping	Office Dept :	Safety

Applicable Dates

Date Raised : 02-Oct-2023

Date Completed : 07-Oct-2023

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	01/Nov/2023
Potential to become a serious accident : Low			Recurrence : Low		

Causes

Poor Housekeeping

Corrective Action

Clean the area and dry completely.

Preventive Action

Include during toolbox meeting that crew should not neglect any oil in working area since very prone to slip hazard.

CONTRIBUTING FACTORS

Root Causes- Personal Factor

Situational Awareness

Substandard Conditions

Greasy/ Oily/ Slippery Surface

Follow Up

On	By	Follow Up	
Before & After Pictures			
Before		After	