

Maritec Tanker Management Private Limited

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

: N/A

Rev Date

Near Miss Details

Gui			
-u	u	u	ioc.

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Morbihan Defect ID: 100

Defect Details

During the passage on 29 november 2023 from DDC TO KOUROU, While 2 AB was Preparing the pilot ladder, one of them was without life vest. Chief officer seen that the AB is doing the job without proper PPE, & called them on radio and told to wear the life vest and then only proceed to the work.

life vest and then only proceed to the work.

After that incident we discuessed this matter in safety meetings also that, while preparing or securing the pilot ladder, Must wear life vest because on that area there is high risk of slip & fall which can lead to a big accident.

Requisition Code:

Categories			
Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Improper PPE	Office Dept:	Safety

Applicable Dates

Date Raised: 03-Dec-2023 Date Completed: 03-Dec-2023

Other Details					
Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI:		Verified On :	

Potential to become a serious accident: Medium Recurrence: Low

Causes

Improper use of PPE, Not aware for situation.

Corrective Action

Discuessed in safety meetings, always use proper PPE, Specially in high risk area of fall overboard wear life vest.

Preventive Action

Always be in proper PPE, While working on deck.

CONTRIBUTING FACTORS

Follow Up

On	Ву	Follow Up	

Before & After Pictures

Near Miss Details Printed On: 14-Dec-2023 1/2

Before

Near Miss Details Printed On: 14-Dec-2023 2/2