



## Maritec Tanker Management

### Near Miss Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

#### Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Bitu River

Defect ID : 15

#### Defect Details

One of Engine room crew hit his foot on workshop skylight door securing fixed hook at the floor and just missed from fall down. The crew wears proper PPE's and helped to protect him from injuring his foot.

Requisition Code :

#### Categories

Primary :	Near Miss	Vessel Dept :	Engine
Secondary :	Inadequate Engineering /Design	Office Dept :	Safety

#### Applicable Dates

Date Raised : 03-Feb-2023

Date Completed : 16-Feb-2023

#### Other Details

Priority :	Urgent	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	13/Mar/2023
Potential to become a serious accident : High			Recurrence : High		

#### Causes

The workshop skylight door fixed hook at the floor is not noticable.

#### Corrective Action

The same painted with bright yellow to get a notice.

#### Preventive Action

All staff have been reminded to keep their eyes and ears open at work place and pay special attention while walking around on the vessel.

#### Applicable Tags

#### Root Causes- Personal Factor

Lack of Knowledge

#### Follow Up

On	By	Follow Up	
----	----	-----------	--

Before & After Pictures

Before

After