

Maritec Tanker Management

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

: N/A

Rev Date

Near Miss Details

$\overline{}$							
G١	ш		2	n	\sim	Δ	•
v	u	u	ш		v	u	٠

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Bitu Atlantic Defect ID: 252

Defect Details

Crew member found out climbing down engine room stairways without holding hand railing.

Requisition Code:

Categories					
Primary :	Near Miss	Vessel Dept :	Engine		
Secondary :	Lack of Situational Awareness	Office Dept:	Safety		

Applicable Dates

Date Raised: 07-Sep-2022 Date Completed: 08-Sep-2022

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI:		Verified On:	08/Sep/2022

Potential to become a serious accident: Low Recurrence: Low

Causes

Lack of situation awareness

Corrective Action

Stopped him, explain him the consequences of his action explain him importance of three point contact

Preventive Action

Brief all crew and explian them three point contact

Applicable Tags

Root Causes- Personal Factor

Lack of Knowledge

Direct Causes- Unsafe Acts

Horseplay / Inappropriate Behavior

Personal Factors

Near Miss Details Printed On: 15-Nov-2022 1/2

Lack of Knowledge					
Substandard Acts					
Failure to observe basic safety rules					
Follow Up					
On	Ву	Follow Up			
Before & After Pictures					
Before		After			

Near Miss Details Printed On: 15-Nov-2022 2/2