

Maritec Tanker Management

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Gui	id	lar	ce
Οu	ıu	u	

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Bitu River Defect ID: 26

Defect Details

The SOPEPE box near manifold was not lashed proeperly and the latch was found damaged which could result in loss of items, damage to box in case of rough weather or rolling.

Requisition Code:

Categories			
Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Other	Office Dept:	Safety

Applicable Dates

Date Raised: 11-Apr-2023 Date Completed: 12-Apr-2023

Other	Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI:		Verified On:	26/May/2023
			·		

Potential to become a serious accident: Low Recurrence: Low

Causes

Corrective Action

Preventive Action

Applicable Tags

Follow Up

On By Follow Up

Before & After Pictures

Before After

Near Miss Details Printed On: 05-Jun-2023 1/2



