



Maritec Tanker Management Private Limited

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Asphalt Teranga

Defect ID : 204

Defect Details

ONE BOLT WAS MISSING AT VAPOUR MANIFOLD'S BLIND FLANGE.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Lack of Knowledge / Skill	Office Dept :	Operations

Applicable Dates

Date Raised : 12-Jan-2024

Date Completed : 12-Jan-2024

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	01/Feb/2024
Potential to become a serious accident : Low			Recurrence : Low		

Causes

Negligence.

Corrective Action

Missing bolt was fitted back in place.

Preventive Action

All deck crew members were briefed on the requirements for bolting down manifold flanges.

CONTRIBUTING FACTORS

Personal Factors

Lack of Knowledge

Follow Up

On	By	Follow Up	
----	----	-----------	--

12/Jan/2024	Ivanov VITALY Staff Code - 10521 - C/OFF	PMN, AB AND OS WERE BRIEFED ABOUT NEED OF FULL BOLTED BLIND FLANGES AND REDUCERS.	
-------------	--	--	--

Before & After Pictures	
Before	After