



Maritec Tanker Management

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Bahama Blue

Defect ID : 55

Defect Details

CHIEF COOK WAS SUDDEN SLIP DUE TO SLIPPERY SURFACE NEAR THE CO2 ROOM AND HE WAS NEARLY TO FALL DOWN.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Other	Office Dept :	Safety

Applicable Dates

Date Raised : 13-Apr-2021

Date Completed : 13-Apr-2021

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	03/Jun/2021
Potential to become a serious accident : Low			Recurrence : Low		

Causes

DUE TO SLIPPERY SURFACE BY OIL OR GRESS.

Corrective Action

THAT AREA WAS CLEAN BY CREW MEMBER AT A TIME.

Preventive Action

a safety meeting was held on that day and a brief introduction given by master about the cleaning, master explained that if any one of crew member see a oil,grease and/or any SLIPPERY surface then clean it at a time.

Applicable Tags**Follow Up**

On	By	Follow Up	
----	----	-----------	--

Before & After Pictures

Before

After