



## Maritec Tanker Management

### Near Miss Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

**Guidance:**

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Bahama Blue

Defect ID : 181

**Defect Details**

During monthly routine check / inspection / greasing of deck cargo hose crane found that the crane wire in starboard aft crane was observe parted / worn at the upper block.

Requisition Code :

**Categories**

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Inadequate Maintenance / Wear and Tear	Office Dept :	Technical

**Applicable Dates**

Date Raised : 14-Feb-2023

Date Completed : 22-May-2023

**Other Details**

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	
Potential to become a serious accident : Low			Recurrence : Low		

**Causes**

Wear & Tier.

**Corrective Action**

Crew members have been warned to refrain from using this crane until wire has been renewed.

**Preventive Action**

Continue following the preventive maintenance more diligently.

**Applicable Tags****Descriptions**

Machinery / Equipment Damage

**Root Causes- Job Factor**

Excessive Wear and Tear

<b>Root Causes- Management Factors</b>
Stores / Spares Issue
<b>Root Causes- Personal Factor</b>
Others
<b>Direct Causes- Unsafe Conditions</b>
Defective Equipment, Machinery or Tools
<b>Direct Causes- Unsafe Acts</b>
Improper Securing / Stowage
<b>Job Factors</b>
Wear and Tear (Not Related to Lack of Maintenance)
<b>Substandard Acts</b>
Improper Lifting
<b>Substandard Conditions</b>
Ropes/ Wires Breaking/ Jamming

**Follow Up**

On	By	Follow Up	
21/May/2023	Valentin MITENKOV   Staff Code - 10552 - MST	Requisition V230041 Wire rope was received in Pointe-a-Pitre, 16.05.2023. Planning to exchange for new wire rope after departure St.Croix on 22.05.2023.	
21/Apr/2023	Nawin Khaware	Advise present status of the vessel, has the issues being rectified or still pending.	
13/Apr/2023	Nawin Khaware	What is the present status of this defective wires, if changed then put the pictures in after renewal section and close out the matter.	
13/Mar/2023	Nawin Khaware	ETC has been changed from "21 Feb 2023" to "30 Mar 2023".	
13/Mar/2023	Nawin Khaware	Please update the latest status, Has the issues being resolved or still pending.	
14/Feb/2023	Valentin MITENKOV   Staff Code - 10552 - MST	Vessel raised requisition BBLU-SDK-V230041 for spare wire rope.	

**Before & After Pictures**

<b>Before</b>	<b>After</b>
---------------	--------------

