



Maritec Tanker Management

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Bahama Blue

Defect ID : 181

Defect Details

During monthly routine check / inspection / greasing of deck cargo hose crane found that the crane wire in starboard aft crane was observe parted / worn at the upper block.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Inadequate Maintenance / Wear and Tear	Office Dept :	Technical

Applicable Dates

Date Raised : 14-Feb-2023

Date Completed : 22-May-2023

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	
Potential to become a serious accident : Low			Recurrence : Low		

Causes

Wear & Tier.

Corrective Action

Crew members have been warned to refrain from using this crane until wire has been renewed.

Preventive Action

Continue following the preventive maintenance more diligently.

Applicable Tags**Descriptions**

Machinery / Equipment Damage

Root Causes- Job Factor

Excessive Wear and Tear

Root Causes- Management Factors
Stores / Spares Issue
Root Causes- Personal Factor
Others
Direct Causes- Unsafe Conditions
Defective Equipment, Machinery or Tools
Direct Causes- Unsafe Acts
Improper Securing / Stowage
Job Factors
Wear and Tear (Not Related to Lack of Maintenance)
Substandard Acts
Improper Lifting
Substandard Conditions
Ropes/ Wires Breaking/ Jamming

Follow Up

On	By	Follow Up	
21/May/2023	Valentin MITENKOV Staff Code - 10552 - MST	Requisition V230041 Wire rope was received in Pointe-a-Pitre, 16.05.2023. Planning to exchange for new wire rope after departure St.Croix on 22.05.2023.	
21/Apr/2023	Nawin Khaware	Advise present status of the vessel, has the issues being rectified or still pending.	
13/Apr/2023	Nawin Khaware	What is the present status of this defective wires, if changed then put the pictures in after renewal section and close out the matter.	
13/Mar/2023	Nawin Khaware	ETC has been changed from "21 Feb 2023" to "30 Mar 2023".	
13/Mar/2023	Nawin Khaware	Please update the latest status, Has the issues being resolved or still pending.	
14/Feb/2023	Valentin MITENKOV Staff Code - 10552 - MST	Vessel raised requisition BBLU-SDK-V230041 for spare wire rope.	

Before & After Pictures

Before	After
---------------	--------------

