



Maritec Tanker Management

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Bahama Blue

Defect ID : 181

Defect Details

During monthly routine check / inspection / greasing of deck cargo hose crane found that the crane wire in starboard aft crane was observe parted / worn at the upper block.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Inadequate Maintenance / Wear and Tear	Office Dept :	Technical

Applicable Dates

Date Raised : 14-Feb-2023

Date Completed : 22-May-2023

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	
Potential to become a serious accident : Low			Recurrence : Low		

Causes

Wear & Tier.

Corrective Action

Crew members have been warned to refrain from using this crane until wire has been renewed.

Preventive Action

Continue following the preventive maintenance more diligently.

Applicable Tags

Descriptions

Machinery / Equipment Damage

Root Causes- Job Factor

Excessive Wear and Tear

Root Causes- Management Factors
Stores / Spares Issue
Root Causes- Personal Factor
Others
Direct Causes- Unsafe Conditions
Defective Equipment, Machinery or Tools
Direct Causes- Unsafe Acts
Improper Securing / Stowage
Job Factors
Wear and Tear (Not Related to Lack of Maintenance)
Substandard Acts
Improper Lifting
Substandard Conditions
Ropes/ Wires Breaking/ Jamming

Follow Up

On	By	Follow Up	
21/May/2023	Valentin MITENKOV Staff Code - 10552 - MST	Requisition V230041 Wire rope was received in Pointe-a-Pitre, 16.05.2023. Planning to exchange for new wire rope after departure St.Croix on 22.05.2023.	
21/Apr/2023	Nawin Khaware	Advise present status of the vessel, has the issues being rectified or still pending.	
13/Apr/2023	Nawin Khaware	What is the present status of this defective wires, if changed then put the pictures in after renewal section and close out the matter.	
13/Mar/2023	Nawin Khaware	ETC has been changed from "21 Feb 2023" to "30 Mar 2023".	
13/Mar/2023	Nawin Khaware	Please update the latest status, Has the issues being resolved or still pending.	
14/Feb/2023	Valentin MITENKOV Staff Code - 10552 - MST	Vessel raised requisition BBLU-SDK-V230041 for spare wire rope.	

Before & After Pictures

Before	After
---------------	--------------

