



# Maritec Tanker Management

## Near Miss Details

Ship File No : N/A  
 Office File No : N/A  
 Form No : N/A  
 Issue : N/A  
 Revision : N/A  
 Rev Date : N/A

**Guidance:**

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Kensington LG

Defect ID : 4

**Defect Details**

AB don't use the life jacket during instalation of Pilot Ladder

Requisition Code :

**Categories**

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Improper PPE	Office Dept :	Safety

**Applicable Dates**

Date Raised : 14-Jul-2023

Date Completed : 14-Jul-2023

**Other Details**

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	
Potential to become a serious accident : Low			Recurrence : Medium		

**Causes****Corrective Action****Preventive Action****Applicable Tags****Root Causes- Job Factor**

Inadequate Work Standards

**Job Factors**

Inadequate Work Standards

**Personal Factors**

Lack of Skill

**Follow Up**

On	By	Follow Up	
19/Jul/2023	Oleg Myronov   Staff Code - 10630 - MST	MORE DISSCUSIONS ON SEFTY COMMITTEE MEETING ABOUT SAFETY ON BOARD AND COMPANY POLICY. FOR ALL DECK CREW REMAIND USED ALL TIME WHEN RIGGING PILOT LADDER LIFEJACKETS AND WEARING OF PROTECTIVE CLOTHING.	

Before & After Pictures	
Before	After