

## **Maritec Tanker Management Private** Limited

Ship File No: N/A Office File No: N/A Form No : N/A Issue

: N/A Revision : N/A Rev Date : N/A

## **Near Miss Details**

Guidance:

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Bitu Express Defect ID: 319

### **Defect Details**

Vessel was underway to Lome. During routine operation of maintenance for Lifeboat Hooks, one crew member observed that another crew who was performing maintenance, work wearing safety belt linked to improper, not to a strong point. There was also moderate swell condition, vessel was slightly rolling.

Requisition Code:

Categories						
Primary :	Near Miss	Vessel Dept :	Deck			
Secondary :	Procedures not Followed	Office Dept:	Operations			

#### **Applicable Dates**

Date Completed: 08-Sep-2023 Date Raised: 15-Aug-2023

Other [	Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI:		Verified On:	06/Oct/2023

Potential to become a serious accident: High Recurrence: Low

# Causes

Human error- Due to a routine working day the crewmember did not pay attention that the safety belt is not properly secured to a strong point.

The crew member was in hurry to finish his job quickly and he did not take consideration potential personal injury and there was a risk to fall in water.

#### **Corrective Action**

Chief Officer requested and advised crew member to make fast the safety belt to a strong point. Always safety first.

## **Preventive Action**

Chief Officer and Bosun explian to all crewmember the importance to identify the risk in all jobs performed and in the future inspect all the crewmembers before and during any special activities that safety measures identified. Near Miss will be discussed in following Safety Meeting

# **CONTRIBUTING FACTORS**

## **Root Causes- Personal Factor**

Lack of Knowledge

## **Direct Causes- Unsafe Acts**

Near Miss Details Printed On: 14-Dec-2023 1/2

Improper Securing / Stowage						
Substandard Acts						
Failure to observe basic safety rules						
Follow Up						
On	Ву	Follow Up				
Before & After Pictures						
Before		After				

Near Miss Details Printed On: 14-Dec-2023 2/2