

Maritec Tanker Management Private Limited

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

Rev Date

: N/A

Near Miss Details

Guidance:

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Saint James LG Defect ID: 338

Defect Details

After the completion of Heving Up the Anchor. Anchor has been found not fully in place. During the Passage it was observed some knock noises.

Requisition Code:

Categories						
Primary :	Near Miss	Vessel Dept :	Deck			
Secondary :	Safe Working Procedures not Followed	Office Dept:	Safety			

Applicable Dates

Date Raised: 15-Nov-2023 Date Completed: 20-Nov-2023

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI:		Verified On:	20/Nov/2023

Potential to become a serious accident: Medium Recurrence: Medium

Causes

Unsafficent Training

Corrective Action

Tool Box meeting, Propper instruction

Preventive Action

Supervision

CONTRIBUTING FACTORS

Root Causes- Job Factor

Inadequate Leadership and / or Supervision

Job Factors

Inadequate Supervision

Near Miss Details Printed On: 14-Dec-2023 1/2

Follow Up							
On	Ву	Follow Up					
Before & After Pictures							
Before			After				

Near Miss Details Printed On: 14-Dec-2023 2/2