



Maritec Tanker Management Private Limited

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Demerara

Defect ID : 88

Defect Details

Observed cartons lying on the galley floor , probably with the purpose of protecting floor from dirty, but doing so, floor become dangerously slippery.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Lack of Situational Awareness	Office Dept :	Crew

Applicable Dates

Date Raised : 15-Oct-2023

Date Completed : 19-Oct-2023

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	01/Nov/2023
Potential to become a serious accident : Low			Recurrence : Low		

Causes

Inadequate assesment of needs and risks

Corrective Action

Cartons removed from the floor.
Briefed galley crew about safety practices.

Preventive Action

The matter will be discussed at next Safety Meeting.

CONTRIBUTING FACTORS

Root Causes- Management Factors

Inadequate Monitoring / Supervision

Root Causes- Personal Factor

Lack of Discipline

Lack of Knowledge
Direct Causes- Unsafe Conditions
Poor Housekeeping
Slippery / Unsteady Work Surface
Direct Causes- Unsafe Acts
Other Substandard Act(s)
Personal Factors
Lack of Knowledge

Follow Up			
On	By	Follow Up	

Before & After Pictures	
Before	After