



Maritec Tanker Management

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Viveka

Defect ID : 47

Defect Details

During recent Discharging operations at Douala Port, ERES Terminal staff was engaged in Collecting cargo samples from COT without Donning Bitumen protective clothing and face shield.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Improper PPE	Office Dept :	Safety

Applicable Dates

Date Raised : 17-Mar-2021

Date Completed : 19-Mar-2021

Other Details

Priority :	Normal	QMS Elements Ref :	M. 2.20 - Near Miss Report	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	19/Mar/2021
Potential to become a serious accident : Medium			Recurrence : Low		

Causes

Non Compliance with safety Precautions during cargo handling.

Corrective Action

As Incident was noticed by duty officer, advised to suspend Sampling Instantly and reported to Chief officer. Shore staff was requested to wear Bitumen Protective Clothing Supplied On board and permitted to resume sampling .

Preventive Action

With Short briefing with Bosun and Pump man further ensured that any staff from ship / shore engaging with cargo operations involving bitumen must be donned with Bitumen protective clothing and a spare Bitumen PPE To stbdy for shore staff as safety precautions.

Applicable Tags**Root Causes- Management Factors**

Inadequate Monitoring / Supervision

Root Causes- Personal Factor

Lack of Skill

Direct Causes- Unsafe Acts

Failure to Use PPE Properly

Job Factors

Inadequate Work Standards

Personal Factors

Lack of Knowledge

Substandard Acts

Failing to use PPE properly

Substandard Conditions

Inadequate or Improper PPE

Follow Up

On	By	Follow Up	
19/Mar/2021	Nawin Khaware	All crew members must be reminded to wear proper PPE for the type of work they are engaged in.	

Before & After Pictures

Before	After
--------	-------